

TOWNSHIP 19 RANGE 08 POINT IDENTIFIER # 700236

PRIMARY CORNER DESCRIPTION C C for Secs. 30 & 31, T19-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

(Original line notes not on record in the Douglas County Surveyors Office)

BLM Resurvey by Norman Price and Thomas Tillman, Cadastral Engineers, under Group #284, Surveyed June/Sept. 1949 - (DCSO records C.S. File 64/76-4

Point for closing cor. of secs. 30 & 31, at intersection of plainly marked original blazed lines, duly identified, the original corner monument has been destroyed by fire.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

T 19 S T 19 S
R 8 W $\frac{S 30}{S 31}$ CC
S 25 R 7 W
1949

from which

A Fir 10" dia., bears N.21¼°E., 48 lks. dist. mkd. T19S R7W S30 CC BT.

A Fir 12" dia., bears S.26°45'E., 37 lks. dist. mkd. T19S R7W S31 CC BT.