

PRIMARY CORNER DESCRIPTION W.C. to 1/4 Cor. Secs. 14 & 23 (West)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13050)

Witness corner bears S.87°37'W., 5.88 chs. from 1/4 cor. Set an iron post, 28" long, 2½" dia., 24" in the ground, for a witness point, with brass cap marked:

T19S R9W
WP
S 14
S 23
1958

from which

- A Hemlock, 8" dia., bears N.52 3/4°W., 29½ lks., mkd: X BT.
- A Hemlock, 11" dia., bears S.42 3/4°W., 4 lks., mkd: X BT.

Douglas Co. Surveyors Office - Stephen J. Flause - Shawn Means - Nathan Reed - April 1980 - C.S. File 61/6-11

Found - 1958 BLM brass cap on 2" iron pipe firmly set & protruding from ground 0.5 ft. properly marked. A 11" Hemlock now a 12" rotted stump 2.5 ft. tall bears S.42 3/4°W., 2.6 ft., blazes are rotted but scribe "BT" is visible with a US Plywood BT tag marked as per record.

NW BT from resurvey is missing.

We also find 2 unrecorded BTs:

- A 17" Hemlock bears S.45½°W., 53.0 ft., with US Plywood BT tag reads reverse bearing & distance N.48°E., 53.4 ft., scribed "WC T19S R9W S23 on a single unhealed blaze marked with yellow paint.
- A 17" Hemlock bears S.74°W., 39.6 ft., with US Plywood BT tag reads reverse bearing and distance N.76°E., 39.2 ft., and scribed "WC T19S R9W S23" on a single unhealed blaze marked with yellow paint.

Note - Because of unrecorded nature of BTs we do not retag but leave as found. No other trees available.

Douglas Co. Surveyors Office - Stephen J. Flause - Karen Mosley - 4/13/1981 - C.S. 61/19-36

Found as described in 1980, to cap at corner we **ADD** the stamping as follows (in a lager stamp size than the BLM markings): "W DCSO 1981"