

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 448)

Set a basalt stone, 14x9x6 ins., 9 ins., in the ground for ¼ sec. cor., mkd: ¼ on W. face; and raised a mound of stone, 2 ft. base, 1½ ft. high, N. of cor.
 Old cor. bears South 20 lks., I destroy it.
 * 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

BLM dependent resurvey by Thomas A. Tillman, Robert L. Holm, & Floyd A. Brooks, under Group # 307, Surveyed May 1957 thru Sept. 1958 - (DCSO records Vol. 31 Page(s) 13055)

Point for ¼ sec. cor. of secs. 2 & 11, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

¼	<u>S 2</u>
	S 11
	1957

from which
 A Fir, 18" dia., bears N.87½°W., 13 lks., mkd: ¼ S2 BT.
 A Fir, 17" dia., bears S.87°E., 12 lks., mkd: ¼ S11 BT.

BLM dependent resurvey by Rick A. McMullen, Cadastral Surveyor, under group #1512, surveyed Sept. 1989/June 1990 - (DCSO records Vol. 50 Page(s) 18941-42)

Point for the 1/4 sec. cor. of secs. 2 & 11 at proportionate distance; there is no remaining evidence of the original corner.
 From this point, the ¼ sec. cor. of secs. 2 & 11, erroneously reestablished by Tillman, Holm, and Brooks in 1957, bears S.76°24'W., 0.530 chs., monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd. & witnessed as described in the official record. remove the iron post, destroy marks on the SE. bearing tree, and at the true corner point
 Reset the iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T19S	R9W
1/4	<u>S 2</u>
	S 11
	1990 1957

(Cont. next page)

TOWNSHIP 19 RANGE 09 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which a bearing tree mkd. by Tillman, Holm, and Brooks
A fir, 25 ins. diam., bears S.79½°W., 65½ lks., with
healed blaze.
and a new bearing tree
A fir, 26 ins. diam., bears N.70¼°E., 56 lks., mkd. ¼ S2
BT.
Deposit a white "DEEP-1" magnetic marker at the base of the
iron post.

Please note that this corner is on the Douglas Co. & Lane Co.
line and Lane Co. Surveyor's Office may have more information
concerning this corner.