

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #705 dated April 14, 1899 - (DCSO records Vol. 1 Page(s) 283)

The ¼ sec. cor., established on former survey*, which is a Fir tree, 7" dia., mkd: ¼ S26 on N & 35 on S sides; from which

 A Fir, 8" dia., bears N.64°W., 34 lks., mkd: ¼ S BT.

 A Fir, 18" dia., bears S.21°E., 59 lks., mkd: ¼ S BT.

* 1899 survey is a corrective resurvey of Chandler's 1895 survey. The Orig. 1895 survey was not accepted but some corners were accepted on a case by case basis. Per Eugene's & Coos Bay's BLM offices.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - June 1969 - C.S. File 53/66-38

Reported as not found.

Possibility on this cor. good if you had line - good calls - I could find no blazes or any line. There is quite a bit of old growth in this area. I tried to match up calls for line by dist. between Smith River.

James W. Prochnau - For: US Forest Service - July 29, 1971 - C.S. File 55/206-6 - M 43-22

Found a faint "X" & orig. line blazes.

Found - 32" Fir with overgrown face, opened face & found orig. scribing. This is the formerly 18" fir in the SE quad.

At the proper distance & bearing from the orig. BT, I placed a 2"x36" galv. IP, flanged at the bottom & capped with a br. disk welded on top. The monument projects 6" above ground. I filled in around the pipe monument with stone & packed earth.

I stamp the disk: ¼ S 26
 S 35
 1971
 4185

I established new BTs as follows, each BT has a scribed face & a USFS BT sign breast high & facing monument, BTs set:

 A 24" D.Fir bears S.19°W., 51.0 ft.

 A 36" D.Fir bears N.25°E., 41.75 ft.

continued next page

1

TOWNSHIP 19 RANGE 10 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

DCSO GPS - 8/26/2021 - added 12/29/2021 - C.S. File 67/51-27
Lat: 43°52'46.47" N Long: 123°51'30.51" W

Douglas Co. Surveyors Office - Crew: Stephen Flauser & Jeff Lorsche - 8/18/2021 (Filed 11/8/2022) - C.S. File 67/54-59

Found - A 2½" dia., brass cap marked as described, on a 2" I.D. iron pipe, projecting 12" above ground. 1971
A 39" dia., D.Fir with a previously opened now re-healed blaze; bears S.21°E., 38.9 ft. 1899 rec
A 52" dia., D.Fir w/fully healed blaze, we add side-center nail, tree bears N.25°E., 42.2 ft. 1971
A 36" dia., D.Fir w/fully healed blaze, we add side-center nail. Tree bears S.19°W., 51.8 ft. 1971

New - 48" D.Fir, tree has large healed scar facing corner, could be from blaze search. We add side-center nail. Tree bears N.68°E., 22.1 ft.

Note - USFS metal witness post and sign, bears East 3.5 ft. Monument is near bottom of SE facing slope in an old growth Fir forest. Monument is approx. 85 ft. west from southerly end of National Forest Rd. 23 bridge over the North Fork of Smith River. Compass decl. 14¾°E.