

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION W. 1/4 cor. for Sec. 19 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by J. H. McClung, under Contract #173, dated July 20, 1872 - (DCSO records Vol. 2 Page(s) 548)

Post for ¼ sec. corner, from which
A Fir 5" dia., bears S.10°E., 11 lks. dist.
A Fir 18" dia., bears N.5°W., 20 lks. dist.

GLO Survey by Thos. Todd, under Contract #574, dated May 19, 1891 - (DCSO records Vol. 2 Page(s) 584)

Old ¼ sec. cor. to sec. 19, which is a post, 4" dia., firmly set in the ground mkd. ¼ S on W. face, from which
A Fir 5" dia., bears S.10°E., 11 lks. dist. mkd. ¼ S BT.
A Fir 18" dia., bears N.5°W., 20 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; C Putnam, crew - Jan. 1962 - C.S. File 49/89-19

Found - Fir, now 26", N.5°W., 13.2 ft., chopped open and found good scribing "4".
No trace found of SE. BT.

Set Brass cap at cor. mkd: County Surveyors Office
T 20 S R 6 W
W ¼ S19
R7W | R6W
1962

New BT - 26" D.Fir N.77°E., 14.8 ft. mkd. ¼ S19 DCS BT.
(On County line - Doug. and Lane)

BLM Resurvey by Harvey E. Wofford and Lester E. Fischer, Cadastral Surveyors, under Group #913, Surveyed Aug. 1976/Aug. 1978 - (DCSO records Vol. 40 Page(s) 16068)

At the ¼ sec. cor. of sec. 19 only, perpetuated and recorded by Godfrey in 1962, monumented with an iron post, 1½" dia., firmly set, projecting 10" above ground, with brass cap mkd. in 1962, from which the remaining original bearing tree:

A Fir 26" dia., bears N.5°W., 20 lks. dist. with healed blaze.
and a bearing tree mkd. by Godfrey:
A Fir 30" dia., bears N.77°E., 22 lks. dist., with healed blaze.
Set a 5 ft. steel fence post alongside iron post.

continued next page

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION W. 1/4 cor. for Sec. 19 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Rob Ward - For: Roseburg Resources Co. & Seneca Jones Timber Co. - 3/2001 - M 136-59 & C.S. File 65/36-16 A

Found - 2½" DCSO brass cap properly mkd.
30" D.Fir bears N.7½°W., 12.6' healed face.
30" D.Fir bears N.80¼°E., 14.9' healed face.
New BTs- 10" D.Fir bears N.83 3/4°W., 9.7' blazed, scribed at base "X BT"
30" D.Fir bears S.37 3/4°E., 18.0' blazed, scribed "¼ S19 BT"
Steel post adjacent to corner. All BTs have red painted bands & faces plus yellow BT tag.