

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by J.H. McClung under Contract #173 dated July 20, 1872 - (DCSO rec. Vol. 2 Page(s) 684

Marked stone in place on west slope of ridge, for 1/4 sec. cor.

Douglas Co. Surveyors Office - Milo Godfrey - Feb. 1962 - C.S. File 49/89-38

Reported as searched for & not found.

BLM dependent resurvey by William W. Glenn, Cadastral Surveyor under Group #441 dated May 1962, surveyed June/July 1962 - (DCSO records Vol. 27 Page(s) 11324D)

Point for the 1/4 sec. cor. of secs. 23 & 26, at proportionate dist.; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:

T 20 S R 6 W
1/4 S 23
S 26
1962

from which

- A Fir, 14" dia., bears N.30 1/2°W., 56 1/2 lks., mkd: 1/4 S23 BT.
- A Cedar, 10" dia., bears S.66 1/4°W., 82 lks., mkd: 1/4 S26 BT.

BLM dependant resurvey by Daniel N. Patterson & Craig Wanless, Cadastral Surveyors, Under group #1764 dated Jan. 1995, surveyed Jan./May 1995 - (DCSO records Vol. 52 Page(s) 19706-7)

Point for 1/4 sec. cor. of secs. 23 & 26, at proportionate distance, there is no remaining evidence of the original corner.

Set a stainless steel post, 28" long, 2 1/2" diam., 24" in the ground, with brass cap mkd. T 20 S R 6 W

1/4 S 23
S 26
1995

from which new bearing trees

- A fir, 18" dia., bears N.9°E., 79 1/2 lks., mkd. 1/4 S23 BT.
 - A hemlock, 15" dia. bears S.71°W., 57 1/2 lks. mkd. 1/4 S26 BT.
- Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

continued next page

TOWNSHIP 20 RANGE 06 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From this point, the ¼ sec. cor. of secs. 23 & 26, erroneously reestablished by Glenn in 1962, bears S.25°22'E., 0.107 chs.; monumented with an iron post, 2½" diam., firmly set, projecting 2" above ground, with brass cap mkd. and witnessed as described in the official record. Remove the marks from the 1962 brass cap and remark the brass cap AM 7.09 FT 1995 and an arrow pointing toward the corner, no marks were removed from the bearing trees due to the size and condition of them.

Les Roberts - Seneca Timber - Apr. 1996 - M 123-60

Found - Amended 1962 BLM Iron pipe and Brass cap true corner, bears N.26°W., 7.05' (data from Eugene BLM office)
18" Cedar, S.65°W., 53.7' (scar vis), 1962 B.T.
18" Fir, N.32°W., 37.1' (scar vis), 1962 B.T.