

TOWNSHIP 20 RANGE 07 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thos. E. Todd under Contract No. 574 dated May 19, 1891 - (DCSO recs. Vol. 2 Page(s) 614)

Set sandstone 20x14x7", 16" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which

A fir, 14" dia., bears N.19°W., 21 lks., mkd: ¼ S BT.

A cedar, 20" dia., bears S.30°E., 20 lks., mkd: ¼ S BT.

Ronald L. Rice - For: Oxbow Timber 1 LLC - May 2014 - M168-5

No evidence of the ¼ cor. was recovered. The missing ¼ cor. was set at proportionate position based the 1892 GLO rec

Set - 2½" Dia. alum. cap on 5/8"x30" rebar marked as shown with the following accessories;

12" D.Fir bears S.11°E., 23.4' scribed "¼ S16 BT"

15" D.Fir bears S.21°W., 14.6' scribed "¼ S16 BT"

15" D.Fir bears S.88°W., 16.3' scribed "¼ S9 BT"

16" D.Fir bears N.34°E., 34.8' scribed "¼ S9 BT"

Steel post adjacent to corner

T20S R7W

¼ $\frac{S\ 9}{S16}$

2014

54633LS