

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20, & 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Pages 484-5)  
-----

Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 16, 17, 20, & 21, mkd. T 20S S 16 on NE, R 8W S 21 on SE, S 20 on SW, S 17 on NW face, with 4 notches on E & 3 on S edge; from which  
Maple, 24" dia. bears N.56°E. 87 lks. mkd: T20S R8W S16 BT  
Maple, 7" dia. bears S.41°E., 26 lks. mkd: T20S R8W S21 BT  
Fir, 40" dia., bears S.48°W., 69 lks. mkd: T20S R8W S20 BT  
Maple, 24" dia. bears N.61°W. 36 lks. mkd: T20S R8W S17 BT

BLM dependent resurvey by Thomas A Tillman, Raymond M. Bicknell, Han W. Thielsen & Joseph S. Gawron, Cadastral Engineers, under Group No. 305 surveyed Aug. 1953 thru Sept. 1954 - (DCSO recs. Vol. 29 Page(s) 12374)  
-----

The cor. of secs. 16, 17, 20, & 21, determined at record bearing & dist. from the remaining orig. BTs:  
A decayed fir snag, 40" dia., bears S.48°W., 69 lks., with no marks remaining.  
A Maple, 30" dia. bears N.61°W. 36 lks., marked with a healed blaze.

At the corner point  
Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap marked  

T20S	R8W
S 17	S 16
S 20	S 21

1954 from which new BTs

A maple, 18" dia., bears N.4¾°E., 96 lks., mkd: T20S R8W S16 BT.  
A maple, 15" dia., bears S.28¾°E., 64 lks., mkd: T20S R8W S21 BT.  
A hemlock, 21" dia., bears S.59¼°W., 85 lks., mkd: T20S R8W S20 BT.

BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jolley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16741-2)  
-----

The corner of secs. 16, 17, 20 & 21, monumented with an iron post, 2" dia., firmly set, projecting 6" above ground with brass cap (properly) mkd.  
from which the remains of the orig. BTs  
A sawed fir stump, 40" dia., bears S.48°W., 72 lks., no marks remaining on burned blaze. (Rec. 69 lks.)  
continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 16, 17, 20, & 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A root hole, bears N.61°W. 36 lks., with a down Maple, alongside, 30" dia., with healed blaze and the remains of the BTs marked in 1954  
A root hole, bears S.28¾°E., 64 lks., with a down maple alongside, 16" dia., no marks remaining on decayed blaze.  
A hemlock snag, 27" dia., bears S.59¼°W., 85 lks., with burned blaze. Rescribed T20S R8W S20 BT on new blaze. and new BTs  
A sawed & burned fir stump, 48" dia., bears N.25°E., 187 lks., mkd: T20S R8W S16 BT.  
A maple snag, 20" dia., bears S.79°E., 159 lks., mkd: T20S R8W S21 BT.  
A sawed & burned fir stump, 65" dia., bears N.65°W., 79 lks., mkd: T20S R8W S17 BT.  
Set a 5 ft. steel fence post alongside the iron post.

Robert Dean, LS 1808 & Wm. J. Ruppert, LS 866 - For: International Paper Co. - 3/30/1983 - M93-80 & C.S. 58/204(N)  
-----  
Found - 1¼" galv. IP w/2½" GLO BC mkd: T20S R8W S17 S16 S20 S21 1954, from which  
50" fir stump w/T20S R8W S16BT visible bears N.23°56'E., 123.5 ft. (rec. per 1967 remonumentation N.25°E., 123.42 ft.)  
New BTs- 7" D.Fir, scribed T20S R8W S20 BT, bears S.52°25'W., 12.7 ft.  
7" D.Fir, scribed T20S R8W S17 BT, bears N.68°34'W., 37.0 ft.  
6" D.Fir, scribed T20S R8W S16 BT, bears N.14°27'E., 38.9 ft.  
7" D.Fir, scribed T20S R8W S21 BT, bears S.37°07'E., 38.6 ft.

Ronald L Rice - For: Oxbow Timber 1 LLC - Dec. 2014 - C.S. File 65/88-1  
-----  
Found - 1954 GLO brass cap with the following accessories:  
15" D.Fir bears S.52°25'W., 12.7' - healed face.  
20" D.Fir bears N.68°34'W., 37.0' - healed face.  
20" D.Fir bears N.14°27'E., 38.9' - healed face.  
19" D.Fir bears S.37°07'E., 38.6' - healed face.  
Record 50" fir not searched for steel post adjacent to corner.