

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

| |
|--|
| <p>GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO records Vol. 2 Pages 469-70)</p> <p>-----</p> <p>Set post, 4" dia., 4 ft. long, in mound of stone, 18" high, 3 ft. sq. at base, for qr. sec. cor., marked ¼ S on W face. No witness trees.</p> |
| <p>BLM dependent resurvey by Thomas A Tillman, Raymond M. Bicknell, Han W. Thielsen & Joseph S. Gawron, Cadastral Engineers, under Group No. 305 surveyed Aug. 1953 thru Sept. 1954 - (DCSO recs. Vol. 29 Page(s) 12362)</p> <p>-----</p> <p>Point for the ¼ sec. cor. of secs. 1 & 2, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 28" in the ground with brass cap marked:</p> <p style="text-align: center;">¼ S 2 S 1 1954</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 12" dia., bears S.41½°E., 26 lks., mkd: ¼ S1 BT.</p> <p style="padding-left: 40px;">A fir, 18" dia., bears S.81½°W., 11 lks., mkd: ¼ S2 BT.</p> <p>The ¼ sec. cor. falls on a spur, slopes S.60°E.</p> |
| <p>BLM remonumentation of Orig. corner points by Wm. W. Glenn, C. Albert White, & James E. Jelley, Cadastral Surveyors, under Group #s 350 & 635, surveyed April & May 1967 (DCSO records Vol. 43 Page(s) 16724)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 1 & 2, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap properly mkd.</p> <p>from which BTs marked in 1954</p> <p style="padding-left: 40px;">A fir, 14" dia., bears S.44°E., 26 lks., with healed blaze. (Rec. S.41½°E.)</p> <p style="padding-left: 40px;">A fir, 24" dia., bears S.78½°W., 11 lks., with healed blaze. (Rec. S.81½°W.)</p> |
| <p>Fd. Ok by Les Roberts, Dec. 1986, M103-63</p> |
| <p>BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23184-5)</p> <p>-----</p> <p>The ¼ sec. cor. of secs. 1 & 2, monumented with an iron post, 1" dia., firmly set, projecting 9" above ground, with a brass cap (properly) mkd.</p> <p>continued next page</p> |

TOWNSHIP 20 RANGE 08 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

from which the remains of the bearing trees mkd. by Tillman, et al. in 1953-54

A decayed fir stump, 24" dia., bears S.44°E., 17.2 ft., no marks visible.

A decayed fir stump, 24" dia., bears S.78½°W., 7.3 ft., with a healed blaze.

and new bearing trees

A white fir, 7" dia., bears S.85½°E., 19.3 ft., mkd. ¼ S1 BT.

A white fir, 7" dia., bears S.83°W., 4.4 ft., mkd. ¼ S2 BT.

A steel fence post is alongside the cor.

Fd as per rec. by D Edwards 4/2019, M175-39

Set a 6' steel post 2 ft S.1°W.