

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for sec. 36 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Pages 322-23)

Set a sandstone 16x12x8 ins., 12" in the ground for ¼ sec. cor. mkd. ¼ on N. face; from which

A Fir 20" dia., bears N.52½°W., 46 lks. dist., mkd. ¼ S BT

A Fir 24" dia., bears S.89°E., 29 lks. dist. mkd. ¼ S BT.

This cor. stands on S. slope of a rocky point.

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 1 Pg 368-69)

The ¼ sec. cor., which is a stone 8x10x6 ins., above the ground, mkd. ¼ on the N. side; from which

A Fir 24" dia., bears N.52½°W., 46 lks. dist. mkd. ¼ S BT

A Fir 30" dia., bears S.87°E., 29 lks. dist. mkd. ¼ S BT.

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12455)

The ¼ sec. cor. of sec. 36 only, monumented with a shattered sandstone 16x12x8 ins., with no marks remaining, loosely set in a small mound of stone, from which the original BTs:

An uprooted Fir 48" dia., plainly blazed and healed, the stump hole of which bears N.52½°W., 46 lks. dist.

A Fir 48" dia., bears S.89°E., 29 lks. dist. mkd. ¼ S BT on bark blaze. (Gesner rec., bears S.87°E.)

At the corner point

Set an iron post, 16" long, 1" dia., 8" in a drill hole in solid rock, with brass cap mkd: ¼ S 36

1954

from which new bearing trees:

A Fir 31" dia., bears N.9°45'E., 72 lks. mkd. ¼ S36 BT.

A Fir 8" dia., bears N.70½°W., 26 lks. mkd. ¼ S36 BT.

Reset the sandstone alongside the iron post.

Fd. OK, and used in BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #'s 350 & 511, surveyed Apr. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14223)

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2286, surveyed 10/2009 - (DCSO rec Vol 56 Pg 22334)

The ¼ sec. cor. of sec. 36 only, on the S. bdy. of T20S R9W, remonumented by Tillman and Gawron in 1953-54, utilized by Peterson in 1966-67, and rehabilitated by Forkner in 2006-09;

continued next page

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for sec. 36 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

monumented with an iron post, 1" dia., firmly set in solid rock, projecting 4" above the surface of the rock, with a brass cap (properly) mkd.
from which the remains of the BTs mkd. by Tillman and Gawron
from which the remains of the BTs mkd. by Tillman and Gawron
A decayed fir stump, 31" dia., bears N.9¾°E., 47.5 ft., with a healed blaze. (Record, 49.1 ft.)
A decayed fir stump, 6" dia., bears N.70½°W., 17.2 ft., with a healed blaze. (Record, 18.0 ft.)
and the bearing trees mkd. by Forkner
A maple, 8" dia., bears N.8½°E., 46.8 ft., with scribe marks ¼ S36 BT visible on bark and a Mag Nail right side center. (Record, N.9°E., 48.5 ft.)
A fir, 11" dia., bears N.84½°W., 17.2 ft., with illegible scribe marks visible on mostly healed double blaze and a Mag Nail right side center.
Corner is located E., 20 ft., of a spur, slopes S., and W., 70 ft., of a creek, 2 ft. wide, course S. Rock faces from spur to 100 ft. E. of creek.

BLM dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2313, surveyed March/Aug. 2011 - (DCSO records Vol. 58 Page(s) 22907)

The ¼ sec. cor. of sec. 36 only, on the S. bdy. of the Tp., monumented with an iron post, 1" dia., firmly set in solid rock, projecting 4" above the surface of the rock, with a bronze cap (properly) mkd.
from which the remains of the BTs mkd. by Tillman and Gawron in 1953-54
A decayed fir stump, 31" dia., bears N.9¾°E., 47.5 ft., with a healed blaze.
A decayed fir stump, 6" dia., bears N.70½°W., 17.2 ft., with a healed blaze.
and the bearing trees mkd. by Forkner in 2006-09
A maple, 8" dia., bears N.8½°E., 46.8 ft., with scribe marks ¼ S36 BT visible on bark and a Mag Nail on right side center.
A fir, 11" dia., bears N.84½°W., 17.2 ft., with illegible scribe marks visible on mostly healed double blaze and a Mag Nail on right side center.
Corner falls 20 ft. E. of a spur, slopes S., and 70 ft. W. of a creek, 2 ft. wide, course S.

continued next page

TOWNSHIP 20 RANGE 09 POINT IDENTIFIER # 640100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for sec. 36 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23077)

The ¼ sec. cor. of sec. 36 only, monumented with an iron post, 1" dia., firmly set in solid rock, projecting 8" above rock, with brass cap (properly) mkd. from which the remains of the bearing trees mkd. by Tillman and Gawron in 1953-54

A fir stump, 32" dia., bears N.9¾°E., 49.1 ft., with a burned partially healed blaze. (Record, 47.5 ft.)

A decayed fir stump, 10" dia., bears N.70½°W., 18.0 ft., with a healed blaze. (Record, 17.2 ft.)

and new bearing trees

A maple, 7" dia., bears N.9°E., 48.5 ft., mkd. ¼ S36 BT.

A fir, 9" dia., bears N.84½°W., 17.2 ft., mkd. ¼ S36 BT on a double blaze.