

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 32

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO survey by John W. Meldrum, under contract No. 116 dated Dec. 12, 1867 - (DCSO records Vol. 1 Page(s) 179)</p> <p>-----</p> <p>Set ¼ sec. post; from which A Hemlock, 10" dia., bears N.15°E., 20 lks. A Hemlock, 9" dia., bears S.15°W., 14 lks.</p>
<p>Roy Gibson - June 1957 - C.S. File 42/275</p> <p>-----</p> <p>No trace of orig. corner was found. corner set by proportional measurements. Set a post, from which; 40" Fir, bears N.17°W., 37.0 ft. 8" Maple bears S.43°E., 14.8 ft.</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Peron - May 1968 - C.S. File 53/66-59</p> <p>-----</p> <p>Found - 3"x3"x48" sq. post & BTs as recorded by Roy Gibson in 1957 by proportional measurement. 40" now 42" Fir sawed stump, N.17°W., 37.0' scribed. 8" now 10" Maple, alive, leaning badly, S.43°E., 14.8 ft. scribe visible.</p> <p>Set - Brass cap at Gibson's corner point mkd: COUNTY SURVEYORS T20S R10W OFFICE 1968 ¼ <u>S 29</u> S 32</p> <p>6" Hemlock N.18°W., 19.2 ft. mkd: ¼ S29 CS BT. 4" Hemlock S.9°E., 30.8 ft. mkd: ¼ S32 CS BT.</p> <p>Note - This corner lies on spur sloping NW approx. 300 ft. E. of creek, course NW in dense brush.</p>
<p>Jerry Estabrook - For: Rayonier- Aug. 2018 - M174-60</p> <p>-----</p> <p>Found - A 1½" IP WITH 2½" brass cap (properly) marked BTs - AN 8" maple wind fall bears S.43°E., 14.8'. A 10" Maple stump, one of multiple live trunks, with tag bears S.12°E., 22.9'. No record of this BT. A 4" Hemlock wind fall, with face and tag bears S.09°E., 30.8'. A 27" hemlock, with healed face, tag and new X -chop bears N.18°W., 19.2'. A 42" Fir stump, with possible healed face bears N.17°W., 37.0'.</p> <p>New BT - A 13" fir, face scribed "S¼ S29 BT" with X-chop and tag bears N78'E 17.6' to a spike at side center.</p> <p>Lat. And Long. Per GARMIN ETREX hand held GPS N: 43°47'47.4" W: 123°55'01.9"</p>

