

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 541100

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 2 only, T21-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (Group #36) (surveyed 1919) - (DCSO records Vol. 1 Page(s) 258) and (Dup. Pg. 1063)

-----  
Set an iron post 3 ft. long, 1" dia., 26" in the ground for  
1/4 sec. cor. of sec. 2 only, with brass cap mkd:  $\frac{1}{4}$  S 2  
1919

from which  
A Wild Cherry 12" dia., bears S.14°E., 30 lks. dist. mkd.  
 $\frac{1}{4}$  S2 BT.  
A Maple 6" dia., bears S.7°W., 10 lks. dist. mkd.  $\frac{1}{4}$  S2 BT.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11667)

-----  
The 1/4 sec. cor., monumented with an iron post, 1" dia., 8" above ground, firmly set, with brass cap mkd. in 1919. No trace of 1919 bearing trees remains. The iron post is rusted nearly through; in its place,  
Set in iron post 3 ft. long, 1" dia., 28" in the ground with brass cap mkd:  
 $\frac{1}{4}$  S 2  
1951

from which new bearing trees:  
A Fir 60" dia., bears S.6°E., 96 lks. dist. mkd.  $\frac{1}{4}$  S2 BT  
A Hemlock 20" dia., S.47°W., 55 lks. dist. mkd.  $\frac{1}{4}$  S2 BT.  
Deposit the old iron post at the base of the new iron post.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew May 1968 - C.S. File 54/1-10

-----  
Found - No trace of brass cap, but 1951 BTs as follows:  
60" now 60" D.Fir, S.6°E., 63.4 ft alive, blaze pitched over and healing.  
20" now 26" Hemlock, alive, S.47°W., 36.3 ft. scribe marks visible on partially healed blaze.  
Set brass cap at cor. mkd: County Surveyors Office 1968  
T20S  
T21S R10W  $\frac{1}{4}$  S 2

Set 6 ft. steel fence post alongside brass cap.  
The 1/4 cor. of sec 35, T20-10, bears N.87 3/4°W., 13.9 ft.  
This cor. lies on edge of new logging road, course N.30°W & S.30°E.  
(Cont. Next Page)

TOWNSHIP 20 RANGE 10 POINT IDENTIFIER # 541100

PRIMARY CORNER DESCRIPTION N. 1/4 Cor. for Sec. 2 only, T21-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd Ok by DCSO 2/1970 C.S. File 54/1-20A (added 3/18/2019) C.S. brass cap on edge of roadway & BTs in good condition
Fd. OK and used in BLM Resurvey by Harvey Wofford, Cadastral Surveyor, under Group #1468 - surveyed Oct. 1988/June 1989 - (DCSO records Vol. 50 Page(s) 19096)