

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 773)

Set ¼ sec. post, from which
A Fir 12" dia., bears N.17°E., 36 lks. dist.
A Fir 10" dia., bears S.10°E., 102 lks. dist.

J.W. Cole, Deputy - Wit: P.D. Wolford; Frank Warren - Sept. 30, 1920 - Field Book 48 Pgs. 55 & 56; (and "old" corner book, page 9)

I renewed corner from the dead stub of original bearing tree, S.10°E., 67.3 ft. No trace of other BT to be found.
Set a 4" x 4" x 36" Post, from which
A Cedar 15", bears S.60°E., 109 lks.
A Fir 24" bears N.34°E., 54 lks.

Glen McChesney - For: Weyerhaeuser Co. - Jan. 21, 1960 - C.S. File 53/104-4

Found - 1856 post, gone.
No trace, 12" Fir, NE.
Found 10" Fir S.10°E., 102 lks., low 4", remains, rotted wood, bark.
1920 post, gone.
1920 15" Cedar, stump, lower face scar visible, S.60°E., 109 lks.
1920 36" badly rotted stump, face rotted away, N.34°E., 54 lks.
Set 1" x 30" alum. pipe set by distance from 1920 BTs.
Accessories added:
12' Fir S.19°W., 37.5 ft. with "W" nail/plate.
14" Fir, N.20°W., 12.3 ft. with "W" nail/plate.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 26, 1966 - C.S. File 54/14-24

Found 1" alum. pipe, Weyerhaeuser BTs and stumps of BTs as recorded by Cole, 1914, as follows:
15" now 30" Cedar stump, S.60°E., 71.9 ft. Open and find "T" scribe and reverse.
24" now 30" Fir, badly rotted stump, N.34°E., 35.6 ft., no scribe found.

(Cont. Next Page)

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set Brass cap at cor. mkd: County Surveyors Office
(Set alongside alum. pipe) T 21 S R 4 W

$\frac{1}{4}$ $\frac{S}{S}$ $\frac{4}{9}$
1966

Scribe Weyerhaeuser BTs:

18" D.Fir N.20°W., 13.1 ft. mkd. $\frac{1}{4}$ S4 CS BT.

16" D.Fir S.19°W., 38.3 ft. mkd. $\frac{1}{4}$ S9 CS BT.

Fd. OK, April 1990 - M 110-2