

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; 34 & 35, T20-4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

**ON COUNTY LINE BE SURE TO CHECK WITH
LANE CO. SURVEYORS OFFICE**

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 747)

Set post cor. of secs. 2, 3, 34 and 35, from which
A R.Fir 8" dia., bears S.20°E., 208 lks. dist.
A R.Fir 8" dia., bears N.61°E., 71 lks. dist.
A R.Fir 30" dia., bears S.28°W., 258 lks. dist.
A Redwood 36" dia., bears N.68°W., 243 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Jan. 6, 1969 - C.S. File 54/14-43

Found - Monel pipe and old mound of stone at corner.
Orig. 8" Fir now 40" sawed stump, S.20°E., 137.3 ft., no scribe.
Orig. 8" Fir now 38" snag, N.61°E., 46.9 ft., open and find scribe.
No trace of other original bearing trees.

Set Brass cap at cor. mkd: County Surveyors Office
(Reset pipe alongside) T20S R4W S 34 | S 35
T21S R4W S 3 | S 2

1969

New BTs- 12" D.Fir S.25°W., 11.0 ft. mkd. T2S R4W S3 DCS BT ("W" nail)
13" D.Fir N.71°W., 11.6 ft. mkd. T20S R4W S3 DCS BT ("W" nail.)
8" D.Fir N.35°E., 9.8 ft. mkd. T20S R4W S35 DCS BT.
15" D.Fir S.60°E., 17.9 ft. mkd. T21S R4W S2 DCS BT. ("W" nail)

This corner fd & recorded in C.S. 54/14 by Weyerhaeuser(?)
(C.S. 54/14-32A is a 12/12/1967 DCSO report -added 12/26/2017)

Cor. Fd. and used in BLM Resurvey by Floyd Brooks; Gordon Popken; Gary Oviatt; Timothy Kent, Cadastral Surveyors, Under Group #724, Surveyed Aug. 1970 - (DCSO records Vol. 37 Page(s) 15276-77)

Fd. OK, Feb. 27, 1987 by Guile - M 103-68 & C.S. File 63/45
Fd. OK, Oct. 4, 1994 by C. Guile - M 120-70

continued next page

TOWNSHIP 21 RANGE 04 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3; 34 & 35, T20-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Craig L. Wanless & Daniel N. Patterson, Cadastral Surveyors, under Group #1577, Surveyed April 1991/April 1993 - Filed Jan. 12, 2004 DCSO - C.S. File 65/49-8 A-I

The cor. of secs. 2, 3, 34, & 35, monumented with an iron pipe, 1" dia., firmly set, projecting 12" above, with brass cap (properly) mkd.

from which the remains of an orig. BT

A fir stump, 38" dia., bears N.61°E., 71 lks., with decayed blaze & a nail with "W" embossed on the head. and the remains of BTs mkd. by McChesney, Weyerhaeuser Timber Co. Land Agent in 1958, remarked by Tracy in 1968 & reported by Brooks Popken, Oviatt, & Kent:

A fir, 9" bears N.31°E., 15 lks., with healed double blaze. (Rec. N.35°E.)

A sawed fir stump, 19" dia., bears S.58°E., 27 lks., with healed blaze. (Rec. S.60°E.)

A sawed fir stump, 14" bears S.29°W., 16½ lks., with healed double blaze. (Rec. S.25°W.)

A sawed fir stump, 15" dia. bears N.71°W., 17½ lks., with healed double blaze.

and new BTs

A fir, 11" dia. bears S.7°W., 206 lks. mkd: T21S R4W S3 BT

A fir, 22" dia., bears N.8½°W., 29½ lks., mkd: T20S R4W S34 BT.

**ON COUNTY LINE BE SURE TO CHECK WITH
LANE CO. SURVEYORS OFFICE**