

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30; & 25, T21-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCS0 records Vol. 2 Page(s) 691)

-----  
Set ¼ sec. post, from which  
A Fir 40" dia., bears S.60°E., 20 lks. dist.  
A Fir 6" dia., bears S.45°W., 84 lks. dist.

-----  
Wilford N. Haines, #239 - For: John Woolley - 1955 - C.S. File 42/77 and M 12-32

-----  
Let Lot Marker.  
Found - 40" Fir snag, S.60°E., 20 lks.  
Scribed- 5" Fir N.33°E., 8.9 ft.  
18" Fir N.45°W., 27.2 ft.

-----  
Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy; C. Putnam, crew - Nov. 2, 1961 - C.S. File 49/143-7

-----  
Found - Haines "T" iron & cap at fence cor - fences E, W & S  
Badly burned old fir stump bears S.60°E., 13.2 ft.  
No scars or scribing fd.  
From monument set by Haines:  
24" Fir bark scribed "¼S" (scar below) bears N.47°W., 27.8 ft.  
8" Fir with scar nearly closed bears N.25°E., 9.0 ft

-----  
Fd. OK, June 1965 (no record source given, probably DCS0)

-----  
Harvey Christensen - For: Seneca Jones Timber Co. - May 2007 - M153-23

-----  
Found - 1" "T" iron with brass cap (Haines) 0.8 ft above grade.  
BTs - 14" D.Fir N.30°E., 8.9 ft. healed face, (new spike), old BLM tag (9.0')  
NW BT missing, replaced  
3" D.Fir, N.85°W., 6,6 ft. blazed & scribed "X" "BT"  
24" D.Fir S.27°E. 24.2 ft blazed & scribed "¼ S30BT"  
Note - No suitable trees to south west.  
Set - 6' steel post 0.5' east