

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 813)

Set ¼ sec. post, from which
A Fir 8" dia., bears N.75°W., 96 lks. dist.
A Fir 6" dia., bears S.72°W., 90 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Clete Putnam, crew - April 23, 1962 - C.S. File 49/89-57

Found - 1/2" Iron pipe.
15" I.Cedar N.8°W., 16.0 ft. scribing 14 or 15 yrs. old, visible.
13" Fir S.30°W., 9.6 ft. Portions of scribing visible in chopped open scar.
Scribed stake, rotted off, lying beside iron pipe, scribing visible "¼S".
No record of renewal on this corner. No trace of original BTs found.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #1059, surveyed April/Dec. 1981 - (DCSO records Vol. 45 Page(s) 17319)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an alum. post, 28" long, 2 1/2" dia., 24" in the ground, with alum. cap mkd:
T 21 S R 5 W
1/4 $\frac{S\ 29}{S\ 32}$
1981

from which
A Fir 11" dia., bears N.1½°E., 35 lks. dist. mkd. ¼ S29 BT
A Fir 13" dia., bears S.8°E., 30 lks. dist. mkd. ¼ S32 BT.

From this point, a corner established by person(s) unknown, bears N.41°37'E., 0.383 chs. dist., monumented with an iron pipe, 1" dia., firmly set, projecting 6" above ground, from which bearing trees mkd. by person(s) unknown
A Cedar 26" dia., bears N.8½°W., 24 lks. dist., with fragmentary scribe marks visible on opened blaze.
A Fir 26" dia., bears S.30°W., 14½ lks. dist., with fragmentary scribe marks visible on opened blaze.

(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Frank O. Williams; D. Wellman; K. Perkins - For: Weyerhaeuser
Co. - Nov. 2, 1984 - C.S. File 58/300 and M 97-48

CORNER REPORT ONLY

Found - 2½" alum. 1981 BLM cap.
13" Fir S.8°W., 30 lks. (Rec. S.8°E., 30 lks.; tag
reads N.8°E 30 lks.)
11" Fir N.1½°E., 35 lks. as per record. Tag reads
S.1½°W., 30 lks.
1" Iron pipe of unknown origin, bears N.41°37'E.,
0.383 chs. with associated BTs:
26" Cedar N.8½°W., 24 lks.
26" Fir S.30°W., 14½ lks.

Corner lies near top of ridge.

Fd. OK, Feb. 1994 by H. Christensen - M 118-63