

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 540700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 2; & 35, T20-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 783)

Set ¼ sec. post, from which
R.Fir 40" dia., bears N.42°E., 11 lks. dist.
R.Fir 12" dia., bears S.26°W., 52 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Sept. 1965 - C.S. File 54/14-15A

Looked for, not found.

BLM Resurvey by Floyd A. Brooks and Timothy A. Kent,
Cadastral Surveyors, under Group #648, Surveyed Aug.
1967/Sept. 1971 - (DCSO records Vol. 37 Page(s) 15257)

The ¼ sec. cor., determined at record bearing and distance
from the remains of the original bearing trees:

A double Fir 52" dia., bears N.42°E., 11 lks. dist., with
healed blaze.

A Fir snag 27" dia., bears S.26°W., 52 lks. dist., with
scribe mark B visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 20" in the ground,
with brass cap mkd:

T 20 S R 5 W

1/4 $\frac{S\ 35}{S\ 2}$

T 21 S

1968

from which new bearing trees

A Fir 7" dia., bears N.67½°E., 57 lks. dist. mkd. ¼ S35
BT.

A Fir 9" dia., bears S.41°E., 35 lks. dist. mkd. ¼ S2 BT