

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 797)

Set ¼ sec. post, from which
A Fir 8" dia., bears N.73°W., 57 lks. dist.
A Fir 12" dia., bears N.38°E., 10 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Aug. 16, 1965 - C.S. File 54/14-13A

Looked for, not found.

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20407)

The ¼ sec. cor. of secs. 13 & 14, determined at record bearing and dist. from the remains of an original bearing tree.

A sawed decayed fir stump, size indeterminate, bears N.38°E., 10 lks., with scribe marks BT visible on remains of pitch stub.

At the corner point

Set a stainless steel post, 28", long, 2~" diam., 27" in the ground, with brass cap mkd.

T21S R5W
¼
S 14|S 13
1996

from which new bearing trees

A fir, 5" diam., bears N.55¼°E., 14 lks., mkd. ¼ S13 BT.

A fir, 37" diam., bears N.75°W., 9 lks., mkd. ¼ S14 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.