

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & 36, T20-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 783)

Set ¼ sec. post, from which
A R.Fir 24" dia., bears N.5°W., 54 lks. dist.
A R.Fir 28" dia., bears S.12°W., 20 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Sept. 1965 - C.S. File 54/14-17A

Looked for, not found

BLM Resurvey by Floyd A. Brooks and Timothy A. Kent, Cadastral Surveyors, under Group #648, Surveyed Aug. 1967/Sept. 1971 - (DCSO records Vol. 37 Page(s) 15255-56)

The ¼ sec. cor., determined at record bearing and distance from the remains of the original bearing trees:

A sawed Fir stump 32" dia., bears N.5°W., 54 lks. dist., with scribe marks BT visible on opened blaze.
A sawed Fir stump 29" dia., bears S.12°W., 20 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 20 S R 5 W
1/4 $\frac{S\ 36}{S\ 1}$
T 21 S
1968

from which new bearing trees

A Fir 10" dia., bears N.33½°W., 18 lks. dist. mkd. ¼ S36 BT.

A Fir 8" dia., bears S.24°W., 18½ lks. dist., mkd. ¼ S1 BT