

PRIMARY CORNER DESCRIPTION Cor. Secs. 4, 5, 8 & 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 732)

-----  
Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 4, 5, 8, & 9, mkd. T 21 S S 4 on NE, R 6 W S 9 on SE, S 8 on SW, S 5 on NW face, with 4 notches on E & 5 on S edge; from which  
Fir, 8" dia., bears N.64°E., 44 lks., mkd: T21S R6W S4 BT.  
Fir, 10" dia. bears S.74°E., 43 lks. mkd: T21S R6W S9 BT.  
Fir, 48" dia., bears N.20°W., 28 lks. mkd: T21S R6W S5 BT.  
Fir, 3½" dia. bears S.16°W., 97 lks. mkd: T21S R6W S8 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Clete Putnam - April 1962 - C.S. File 49/143-25

-----  
Found - Haines "T" iron at corner & 8" Fir, now 36" N.64°E., 29.0 ft. Cut open & fd. good scribing "S R6"  
10" Fir, now 38" S.74°E., 28.4 ft. show good scar.  
Do not open.  
Badly rotted Fir snag bears N.20°W. 18.5 ft No scars or scribing fd. - too much of it rotted away.  
No trace fd. of SW BT.  
Set - Brass cap mkd: COUNTY SURVEYORS T21S R6W S5|S4  
OFFICE, 1962 S8|S9  
Rescribe-38" Fir S.74°E., 28.4 ft. mkd: T21S R6W S9 CS BT.  
New BTs- 30" D.Fir N.80°E., 36.8 ft., mkd: T21S R6W S4 CS BT  
12" D.Fir S.87½°W., 98.0 ft., mkd: T21S R6W S8 CS BT  
25" D.Fir N.1°W., 64.3 ft., mkd: T21S R6W S5 CS BT

Fd. D.Marx - 4/1987 - M105-45

Douglas Co. Surveyors Office - Stephen J. Flause - R.W. Smith - Aug. 10, 1987 - C.S. File 62/45-2

-----  
Found - 1962 County brass cap, properly mkd., on a 1¼" O.D. iron pipe firmly set & protruding 4" above ground  
Haines T-iron buried under fallen log is bent slightly & leaning southeast 0.3 ft. from brass cap position. (found in 1962 ren. not otherwise unrecorded)  
No evidence of original post and stone found.  
An original fir, 8" dia. now a 47" D.Fir DBH with a previously opened now fully re-healed single blaze, N.64°E., 29.0 ft. dist.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 4, 5, 8 & 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

An orig. fir, 10" dia. now a 48" D. fir DBH with a previously rescribed now fully re-healed single blaze bears N.74°E. 28.4 ft. distant (as per rec)  
Possible evidence of an original fir, 48" dia. now a rotted fir, snag 37" DBH, 25 ft. tall previously opened but with no evidence of blaze or scribing bears N.21°W., 20.2 ft. distant. (record N.20°W., 18.5 ft. dist.)  
A 30" D.Fir now 33" DBH, with a fully healed single blaze bears N.80°E., 36.8 ft. (as per record.)  
A 12" D.Fir now 16" DBH, fallen rotting & out of position with a partially healed but rotted double blaze containing some evidence of partial but illegible scribing; indistinct roothole of this tree is near record bearing and distance.  
A 25" D.Fir now 30" DBH with a fully healed single blaze bears N.3½°W., 62.9 ft. (Rec. N.1°W., 64.3 ft.; distance checks well as a slope distance.)  
An unrecorded alder with a 1979 BT tag possibly signed JEJ, is 20" DBH bark scribed T21S R6W S8 BT and bears S.30°E., 19.1 ft. (BT tag records S.29°E., 29 lks.)  
No new monument set or new BTs scribed.  
Monument lies at foot of southerly slope of steep walled flat bottomed draw; and is approx. 70 ft. south of seasonal creek in draw and is approx. 200 ft. southeast from confluence of creek indraw and creek in main canyon coursing southwest.

Fd. Ok by Steve Ness, M121-24 A&B - 10/1994