

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Pages 722-3)

Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 9, 10, 15 & 16, mkd. T 21 S S 10 on NE, R 6 W S 15 on SE, S 16 on SW, S 9 on NW face, with 3 notches on E & 4 on S edge; from which
Maple, 16" dia. bears N.77°E. 49 lks. mkd: T21S R6W S10 BT
Cedar, 8" dia. bears S.16°E., 38 lks. mkd: T21S R6W S15 BT
Hemlock, 18" dia., bears S.61°W., 72 lks., mkd: T21S R6W S16 BT.
V.Maple, 6" dia. bears N.63°W. 44 lks. mkd: T21S R6W S9 BT

Wilford N. Haines - For: Woolley Logging Co. - Dec. 1961 - C.S. File 51/222-1

Found - 6" V.Maple & 18" Hemlock dead.
Set - 1"x1"x36" T iron.
Should be checked
Note - Hand written note "This corner set in error. N.G. Dec. 20, 1966" signed by Wilford Haines.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - July 5, 1962 - C.S. File 49/143-2

Recorded as not found:
As Renewed by Wilford Haines.
Fd. "T" iron & cap.
A Cedar tree (chopped open) with yellow tag on it bears S.16°E., approx. 25 ft. No evidence that it is BT. No trace of any BTs. fd. This renewal is recorded, but I can not find evidence of orig. corner. I did not renew it.
(Note: Godfrey's corner report was added to the corner renewal system 7/29/2002, previously there was just a "not fd." note hand written on Haines's map C.S. File 51/222 by LL & a "?" on the corner renewal visual map. DCSO/JC)

Harvey Christensen - For: Seneca Jones Timber Co. - 1/1999 - M131-17

From the narrative:
The SW corner of Sec. 10 was held as fd. being monumented by Haines in C.S. 51/222 with a 1"x1" T iron with brass washer, the V.Maple & dead Hemlock were not fd. but the orig. 8" Cedar was found at near rec. bearing and distance & tagged with a BLM bearing tree sign. From corner notes:
continued next page

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor Secs 9, 10, 15, & 16

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Found - 1961 1"x1" Haines "T" iron 0.5 ft. above ground.
48" R.Cedar, S.16°E., 24.7 ft. /w old BLM tag, face
chopped out to past center-reblazed & scribed
"T21S R6W S15 BT"
25" R.Cedar S.34°W., 31.1 ft. blazed & scribed "T21S
R6W S16 BT"
32" R.Cedar N.77°W., 88.4 ft. blazed & scribed "T21S
R6W S9 BT"
33" R.Cedar N.21°E., 51.4 ft blazed & scribed "T21S
R6W S10 BT"
Set - 6 ft. steel post 1 ft. North, corner lies about 15
ft. East of drainage.