

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 713)

-----  
Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for gr. sec. cor. marked ¼ S on W face; from which Hemlock, 20" dia., bears S.53°E., 18 lks., mkd: ¼ S BT. Hemlock, 14" dia., bears S.57°W., 25 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Clete Putnam - April 1962 - C.S. File 49/143-29

-----  
Found - Badly rotted hemlock stump S.53°E., 11.9 ft., scribing visible on old face "¼S"  
Badly rotted hemlock stump S.57°W., 16.5 ft. fd. fragment of scribing, part of "B"  
Set - Brass cap at cor. mkd: COUNTY SURVEYORS OFFICE 1962  
T21S R6W ¼ S15|S14  
5" hemlock S.41°W., 10.8 ft., mkd: ¼ S15 CS BT  
5" hemlock N.30°E., 6.0 ft., mkd: ¼ S14 CS BT  
Corner lies on steep NW slope approx. 100 ft. South of small stream.

BLM remonumentation of certain orig. corner points by James E. Jelley, under group #350 surveyed April 1979 - (DCSO records Vol. 43 Page 16478-9)

-----  
The ¼ sec. cor. of secs. 14 & 15, perpetuated & recorded by Godfrey in 1962, determined at record bearing & distance from the remains of the orig. BTs:

A decayed hemlock stump, 30" dia., bears S.53°E., 18 lks., with fragmentary scribe marks visible on decayed blaze. and the remains of BTs mkd. by Godfrey

A root hole, bears N.30°E., 9 lks., with a down hemlock alongside, 5" dia., with fragmentary scribe marks visible on open blaze.

A root hole, bears S.41°W., 16½ lks., with a down hemlock alongside, 5" dia., with fragmentary scribe marks visible on open blaze.

At the corner point

Reset an iron post, 36" long, 1¼" dia., 28" in the ground, with brass cap marked: COUNTY SURVEYORS OFFICE

T 21 S R 6 W

¼ S 15|S 14

1962 from which new BTs

A hemlock, 8" dia., bears N.86°E., 20 lks., mkd: ¼ S14 BT.

A hemlock, 10" dia. bears S.14½°W., 35 lks. mkd: ¼ S15 BT.

continued next page

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 15

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

The position for the county corner monument had changed since 1962, because of a small land slide which necessitated resetting the monument.

Harvey Christensen - For: Seneca Jones Timber Co. - 1/1999 - M131-17

-----  
Found - 1962 DCSO 3,0" B C, 0.3 FT. ABOVE GROUND  
BTs - 13" W. Hem, S.14°W., 21.1 ft., scribing visible  
8" W. Hem, N.86°E., 13.3 ft. (Record), blown down  
12" W. Hem, S.21°E., 24.1 ft. Blazed & scribed "1/4  
S14 BT"  
15" W. Hem, N.55°E., 43.5 ft. Blazed & scribed "1/4  
S14 BT"  
12" W. Hem, N.77°W., 35.0 ft. Blazed & scribed "1/4  
S15 BT  
Set - 6 ft. Steel post 1 ft. North