

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor Secs 14, 15, 22, & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 644-5)

Set post, 6" dia., 4 ft. long, with marked stone, 12" in ground, for cor. to secs. 14, 15, 22, & 23, mkd. T21S S14 on NE, R 7 W S 23 on SE, S 22 on SW, S 15 on NW face, with 2 notches on E & 3 on S edges; from which
 Laurel, 10" dia., bears N.41°E., 30 lks., mkd: T21S R7W S14 BT.
 Laurel, 12" dia., bears S.45°W., 17 lks., mkd: T21S R7W S22 BT.
 Fir, 20" dia., bears S.67°E., 10 lks. mkd: T21S R7W S23 BT
 Fir, 20" dia. bears N.25°W., 30 lks. mkd: T21S R7W S15 BT.

Wilford Haines - July 27, 1955 - C.S. file 42/3 & M1-68

Corner set from old BTs
Set a 1"x1"x36" angle iron with brass cap inscribed Wilford N. Haines #239

Douglas Co. Surveyors Office - Vernon "Ray" Tracy & crew - 5/24/1967 - C.S. File 49/20-19

Found - Orig. 20", now 36" fir, N.25°W. 19.8 ft, alive, shows 2" scribe on prev. opened blaze.
Large hole where SE BT stood. No trace of other BTs
Haines' "T" Iron is set from present out side edge of bark.
Set - Brass Cap at Cor. Mkd: County Surveyors T21S R7W
("T" Iron bears S.25°E. Office S 15|S 14
2.0 ft 1967 S 22|S 23
New BTs- 24" D.Fir N.81°W., 12.7 ft. mkd: T21S R7W S15 CSBT.
30" D.Fir S.78°E., 32.2 ft. mkd: T21S R7W S23 CS BT.
10" Hemlock N.62°E. 13.4 ft. mkd: T21S R7W S14 CS BT
No suitable tree to SW
This corner on SW side of top of spur, sloping south.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J Flause - John Pike - 4/14/1992 - C.S. File 64/24-13

Found - A 2½" dia. 1987 DCSO brass cap on a 1½" O.D. iron pipe protruding 13" above ground. 1967
Haines T-Iron protrudes 17" above ground. 1961
T-Iron bears S.25°E., 2.0 ft. from DCSO BC/IP.
(agrees w/rec,)
Brg's & dists from DCSO BC/IP:
continued next page

PRIMARY CORNER DESCRIPTION Cor Secs 14, 15, 22, & 23

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

20" now 36" 10 ft. high D.Fir stump with gal. cap on top. NO scribing visible in a previously opened blaze, BT bears N.25°W., 18.5 ft. (Rec. N.25°W., 19.8 ft.) Orig. BT.
24" now 26" dia. 7 ft. high D.Fir stump with a fully healed double blaze, bears N.81°W., 12.7 ft. (agrees w/rec)
30" now 36" D. Fir with a fully healed double blaze bears S. 78°E., 32.2 ft. (agrees w/rec)
10" now 15" dia. Hemlock with a fully healed double blaze, bears N.58°E. , 13.4 ft. (Rec. N.62°E. , 13.4 ft., error in compass reading)
No new accessories. No trees to the west. Stumps are in good shape.

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1916, surveyed Aug. 1999/May 2000. (DCS0 rec. Vol. 53 page(s) 20640-1)

The cor. of secs. 14, 15, 22, & 23, perpetuated by Tracy, in 1967; monumented with an iron pipe, 1¼" diam., firmly set, projecting 18" above ground, with brass cap (properly) mkd. from which the remains of an original bearing tree
A sawed and decayed fir stump, 40" diam., bears N.25°W., 19.8 ft., with no marks visible on opened blaze.
and the remains of bearing trees mkd. by Tracy
A hemlock, 20" diam., bears N.60°E., 13.0 ft., with a healed double blaze.
A fir, 35" diam., bears S.77°E., 32.4 ft., with a healed double blaze.
A sawed fir stump, 26" diam., bears N.80°W., 12.3 ft., with a healed double blaze.
and a new bearing tree
A hemlock, 4" diam., bears N.73¾°W., 55.3 ft., mkd. X BT.
There are no suitable trees within limits to SW.

Each new bearing tree has a 2½" X ¼" magnetic nail (Mag Nail) driven at the base on right side-center, unless otherwise described in the corner description.
From this point, a point established as the cor. of secs. 14, 15, 22, and 23, by Haines, in 1955, bears S.25°E., 1.8 ft., monumented with a 1" "T" shaped iron rod, firmly set, projecting 16" above ground, with brass disc, 1" diam., attached to top, mkd. WILFORD N HAINES 239 SURVEY POINT DRAIN ORE, this corner was improperly established and was not utilized in this survey.

cont.

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor. Secs. 14, 15, 22, & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Tony Hostetter - For: Roseburg Resources - 9/2023 - M182-79

Found 1967 DCS0 brass cap and accessories as described by
Moore (BLM) in 1999