

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 and 35 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 2 Page(s) 836)

Marked Hemlock tree, 5" dia., for section corner, from which
A Hemlock tree 12" dia., bears N.50°W., 17 lks.
A Fir tree 50" dia., N.30°E., 45 lks.

Cor. Fd. and used by Wm. Wright, GLO surveyor, contract #486, dated Aug. 1, 1883 (DCSO records. Vol. 2 Page 848)

GLO resurvey by M. Lytle; P. Norseth; T. Tillman; R. Bicknell; J. Gawron & H. Thielsen, Cadastral Engineers, under Group #304, surveyed Aug. 1952-Oct. 1954 (DCSO records Vol. 30 Page(s) 12546-47)

Point for the cor. of secs. 34 and 35 only, determined from the remaining original bearing tree:

A Fir 55" dia., bears N.30°E., 45 lks. dist. showing old scribe marks in the bark.

At the corner point

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with brass cap mkd:

T 21 S R 8 W

S 34 | S 35

S 2

T 22 S R 8 W

1952

from which

A Fir 47" dia., bears N.35½°E., 92 lks. dist. mkd. T21S R8W S35 BT.

A Fir 7" dia., bears N.78½°W., 35 lks. dist. mkd. T21S R8W S34 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone, crew - Sept. 1963 - C.S. File 52/14-31

Found - Brass cap set in 1952, under uprooted 36" Fir.
7" Hemlock now 10", N.78½°W., 23.1 ft. Tree alive and in good condition. (Rec. Fir)

55" Fir N.30°E., 29.7 ft. is now a stump, sawed off 2 ft. above ground.

47" Fir N.35½°E., 60.7 ft. is now a shattered snag.

New BT - 10" Hemlock N.7½°W., 68.0 ft. mkd. T21S R8W S34 CS BT.

No trees available in section 35.

continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 500100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 and 35 only (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #1000, surveyed May 1999/April 2000 - (DCSO rec. Vol. 54 Page(s) 20735-6)

The cor. of secs. 34 and 35 only, on the S. bdy. of the Tp., monumented with an iron post, 2" dia., firmly set, projecting 4" above the ground, with brass cap (properly) mkd. from which the remains of BTs mkd. by Lytle, et. all

A fir snag, 28" dia., bears N.35½°E., 66.3 ft., no marks visible. (Record, 60.7 ft.)

A hemlock, 18" dia., bears N.78½°W., 23.1 ft., with a healed blaze. (Record, fir)

and BT mkd. by Godfrey, Deputy County Surveyor in 1963,

A hemlock, 23" dia., bears N.6¾°W., 70.3 ft., with a healed blaze.

and new bearing tree

A fir, 21" dia., bears N.85°E., 23.4 ft., mkd. T21S R8W S35 BT.