

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 18 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 906-07)

Set a sandstone 12x10x8 ins., 9" in the ground on steep hill side sloping North, for ¼ sec. cor. mkd. ¼ S on the W. face, from which
A Fir 32" dia., bears N.37°W., 10 lks. dist. mkd. ¼ S BT.
A Fir 32" dia., bears S.25°W., 55 lks. dist. mkd. ¼ S BT.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 994-95) and (Dup. Pg. 1030)

Intersect the old ¼ sec. cor., which is a sandstone, firmly set, marked and witnessed as described by the surveyor general. I obliterate marks on the old bearing tree referring to sec. 13 and change this cor. to refer to sec. 18 only and alongside the old cor., Set an iron post 3 ft. long, 1" dia., 26" in the ground, for ¼ sec. cor. of sec. 18 only, with brass cap mkd: ¼
S18
1919

from which
A Fir 30" dia., bears N.42°E., 10 lks. dist. mkd. ¼ S18 BT. (Old BT)
A Fir 36" dia., bears S.66°E., 50 lks. dist. mkd. ¼ S18 BT. (New BT)

Mark Smalley - for: Roseburg Forest Products - Mar. 18, 1997 - C.S. 65/15-9

Found - 1945 GLO IPBC
15" Fir, S.80°E., 17 lks., good - healed face
14" Fir, N.31½°E., 47 lks., good - healed face - tag 7½' up tree
Root hole N.85½°E., 217 lks. - remains of 1945 BT
New Accessories -
11" Fir, N.4°W., 17.3' scribed "¼ BT"
6" Fir, S.12°E., scribed "¼ BT"