

PRIMARY CORNER DESCRIPTION C C for Secs. 4 and 5 only, T22-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1673)

I set sandstone 14 x 12 x 6 ins., 10" in the ground for closing corner to sec. 4 and 5, mkd. C.C. on the S.; 4 grooves on the E.; and 2 grooves on the W. side, from which

A Fir 28" dia., bears S.71°30'E., 103 lks. dist. mkd. T22S R9W S4 BT.

A Fir 8" dia., bears S.52°W., 175 lks. dist. mkd. T22S R9W S4 BT.

A Fir 26" dia., bears N.20°30'E., 42 lks. dist. mkd. C.C. T22S R9W S4 and 5 BT.

V. W. Hosford - For: Evans Products Co. - Aug. 1954 - C.S. File 41/292 and M 10-80

I find the closing cor. to sections 4 and 5. At this corner, I found the original marked stone and 3 original BTs.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Nov. 20, 1975 - C.S. File 57/39-15

Found - 14 x 12 x 6" sandstone, CC marked on one side, 2 grooves on one side, stone badly weathered and laying on surface.

A Fir 26" now 39" dia., bears N.20½°E., 27.7 ft. scribed "CC T22S R9W S", blaze partially opened and burned.

A Fir stump 28", now 39" dia., bears S.71½°E., 69.7 ft. (Rec. 68 ft.), partial blaze below cutting line scribed "BT" (blaze not original as face of blaze falls well outside of record dia.)

A Fir 8", now 35" dia., bears S.53½°W., 115.5 ft. (Rec. S.52°W.) Tree has good blaze.

Set brass cap at C.C. stamped: County Surveyors Office

```

T 21 S R 9 W
  S 32
-----
  S 5 | S 4
    C C
T 22 S R 9 W
  1975

```

Original corner stone on North side of cap with CC on South face.

Corner lies on top of ridge running West.

(Cont. Next Page)

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 271100

PRIMARY CORNER DESCRIPTION C C for secs. 4 and 5 only, T22-9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1281, surveyed Aug/Oct. 1985 - (DCSO records Vol. 48 Page(s) 18194)

Intersect the S. bdy. of Sec. 32, T21S R9W; true point for the closing cor. of secs. 4 and 5.

Set an iron post 28" long, 2½" dia., 24" in the ground with brass cap mkd:

T 21 S R 9 W
 S 32
 S 5 | S 4
T 22 S R 9 W
 CC
 1985

from which

A Fir 6" dia., bears S.72°E., 56 lks. dist. mkd. X BT.

A Fir 6" dia., bears S.75°W., 66 lks. dist. mkd. T22S R9W S5 CC BT.

From this point, the original closing cor. of secs. 4 and 5, bears N.0°01'E., 0.139 chs. dist., recovered and recorded by Hosford in 1954, and perpetuated and recorded by Monrean in 1975, monumented with an iron post, 1¼" dia., firmly set, projecting 3" above ground. (alongside of which is the original sandstone 14 x 12 x 6 ins., firmly set, projecting 6" above ground, mkd. CC on S. face), with 1975 brass cap.

From which the remains of the original bearing trees:

A Fir 40" dia., bears N.20½°E., 42 lks. dist. with scribe marks 9W S25 visible on opened blaze.

A sawed Fir stump 39" dia., bears S.71½°E., 101 lks. dist. with scribe marks BT visible on opened blaze. (Rec. 103 lks.)

A Fir 36" dia., bears S.52°W., 175 lks. dist. with healed blaze.

Add marks AM to brass cap.

Fd. & used on Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19860)