

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 947-8)

Set Fir post, 4½ ft. long, 4" sq., 24" in the ground on hillside sloping NE for ¼ sec. cor., mkd: ¼ S on W face; from which

A Fir, 42" dia., bears N.8°E., 88 lks., mkd: ¼ S BT.
A Cedar, 10" dia., bears N.32°W., 83 lks., mkd: ¼ S BT.

BLM dependent resurvey by Norman J. McDonald, Cadastral Surveyor, under Group #350 April 1963/ - (DCSO records, Vol. 32 Page(s) 13136)

The ¼ sec. cor. of secs. 15 & 16 determined at record distance from the orig. BTs:

A Fir, 48" dia., bears N.5½°E., 88 lks., with fragmentary scribe marks visible on open blaze. (Rec. bearing, N.8°E.)

A Cedar, 25" dia., bears N.31°W., 83 lks., with scribe marks ¼ S visible on partially healed blaze. (Rec. bearing N.32°W)

At the corner point

Set an iron post, 30" long, 2½" dia., 26" in the ground, with brass cap marked:

T21S R9W
¼
S 16|S 15
1963

from which a new BT

A Fir, 50" dia., bears N.76½°E., 61 lks., mkd: ¼ S15 BT.

Ron Quimby - Crew: N. Fromdahl - 1/2020 - C.S. File 65/104-32

Found - BLM brass cap (properly mkd)
50" Fir stump N.76½°E., 40.3 ft. (with tag)
48" Fir stump N.8°E., 58.1 ft., rotted (rec N.5½°E.)
Cedar stub N.31°W., 54.8 ft. rotted.

New - 16" Hemlock N.18°W., 26.3 ft. scribed ¼ S16 BT
20" W.Fir S.88°E., 43.3 ft. scribed ¼ S15 BT
Alum post 5.0 N & 5.0 S

Compass decl. 15½°E.