

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 946-7)

-----  
Set sandstone 14x12x8" 10" in the ground on bank of creek for 1/4 sec. cor., mkd: 1/4 S on the N face from which  
A Hemlock, 20" dia., bears S.26°W., 54 lks., mkd: 1/4 S BT.  
A Maple, 20" dia., bears N.35°W., 32 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14241-2)

-----  
The 1/4 sec. cor. of secs. 15 & 22, monumented with a sandstone 14x12x8", firmly set, 6" in the ground, with no visible marks, from which the orig. BTs:

A Maple, 38" dia., bears N.35°W., 32 lks., with healed blaze.

The stump hole of a fallen & decayed hemlock, 20" dia., bears S.26°W., 54 lks. with no marks visible.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:

1/4 S 15  
S 22  
T21S R9W  
1966

from which a new BT

A Fir, 8" dia., bears S.62°E., 12 lks., mkd: 1/4 S22 BT.

Deposit the orig. stone alongside the iron post.

Fd. ok by BLM dependent resurvey by John A. Farmer, Cadastral Surveyor, under Group #1399, surveyed Aug./Sept. 1987 - (DCSO records Vol. 48 Page(s) 18455)