

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19 only, T21-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #486, dated August 1, 1883 (DCSO records Vol. 2 Page(s) 889)

Set post 6" dia., 4 ft. long, with marked stone 12" in ground for cor. to secs. 13, 24, 18 and 19, marked T21S S18 on NE.; R8W S19 on SE.; R9W S24 on SW.; S13 on NW. faces with 3 notches on N. & S. edges, from which

A Fir 8" dia., bears N.80°E., 40 lks. dist. mkd. T21S R8W S18 BT.

A Fir 6" dia., bears S.59°E., 32 lks. dist. mkd. T21S R8W S19 BT.

A Fir 12" dia., bears S.72°W., 45 lks. dist. mkd. T21S R9W S24 BT.

An Alder 12" dia., bears N.54°W., 39 lks. dist. mkd. T21S R9W S13 BT.

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 920)

The Sec. Cor. to 18 & 19, which is a post 30" above ground, 4" sq. marked T21S S18 on the NE.; R8W S19 on the SE.; R9W S24 on the SW.; and S13 on the NW. faces, with 3 notches on the N. and S. edges, from which

A Hemlock 12" dia., bears N.80°E., 40 lks. dist. mkd. T21S R8W S18 BT.

A Hemlock 16" dia., bears S.72°W., 46 lks. dist. mkd. T21S R9W S24 BT.

The other bearing trees had been destroyed, I marked

A Fir 6" dia., bears S.45°E., 38 lks. dist. mkd. T21S R8W S19 BT.

GLO Resurvey by Norman D. Price and George Rigby, Cadastral Engineers, under Group #282, Surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11384)

(After a careful investigation, it is developed that Gesner's recorded retracement of this line is entirely fictitious, that it is a deliberate fabrication on his part for the purpose of justifying his own work and creating a limiting boundary for T21S R9W., and is therefore rejected as a suitable basis for restoration of lost corners referring to T21S R8W.) (Vol. 27 Pg. 11379)

The cor. of secs. 18 & 19, the locus of which is determined at the record bearing and distance from the old NE. and SW. bearing trees.

At the corner point

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19 only, T21-8

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, with brass cap mkd:

T 21 S	T 21 S
R 9 W	S 18
S 13	S 19
	R 8 W

1945

from which

A dead Hemlock 16" dia., bears N.80°E., 40 lks. with face of old blaze burned. (Old BT)

A dead Hemlock 20" dia., bears S.72°W., 46 lks. mkd. BT S24 T21S R9W (Old BT)

A Fir 40" dia., bears N.45¼°E., 151 lks. mkd. T21S R8W S18 BT. (New BT)

A dead Fir 60" dia., bears S.66¼°E., 62 lks. dist., mkd. T21S R8W S19 BT. (New BT)

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #'s 350 & 511, surveyed Apr. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14208-09)

The Sec. Cor., monumented with an iron post 2" dia., extending 8" above ground, firmly set with brass cap marked in 1945,
 from which bearing trees mkd. in 1945:

A sawed Fir stump 55" dia., bears N.45¼°E., 151 lks. dist., with no marks remaining.

A sawed Fir stump 65" dia., bears S.66¼°E., 62 lks. dist. with scribe marks 21S 19 Bt visible on opened blaze.

and new bearing trees:

A Fir 6" dia. bears N.81°E., 100 lks. mkd. T21S R8W S18 BT

A Fir 7" dia. bears S.54°E., 109 lks. mkd. T21S R8W S19 BT

Fd. Ok by C.Mulkins 10/26/95 - M123-22

Rob Ward - For: Roseburg Resources Co. - April 2002 - M140-10

Found - 2½" GLO brass cap dated 1945

55" D.Fir stump bears N.45¼°E. 151 lks., no visible marks.

65" D.Fir stump bears S.66¼°E. 62 lks. Rotten open face.

15" D.Fir bears N.81°E. 100 lks. -healed face

23" D.Fir bears S.54°E. 109 lks. -healed face

New BT'S-18" D.Fir bears S2.5°W. 8.4' blazed at base, scribed "X BT".

18" D.Fir bears S.85¾°W. blazed at base, scribed "X BT"

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 700403

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19 only, T21-8

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Fd. Ok on BLM dependent resurvey by Aaron M. Graham, Cadastral Surveyor, under Group No. 2011, surveyed Dec. 2002/Feb. 2003 - (DCSO records Vol. 54 Page(s) 20772-3)