

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 12, 1867 (DCSO records Vol. 1 Page(s) 174)

-----  
Set stone 16x14x5 for corner to secs. 4, 5, 32 and 33, from which

A Fir 36" dia., bears S.75°W., 27 lks., lks. dist.  
An Alder 10" dia., bears N.85°E., 87 lks. dist.

H.L. Eppstein, County Surveyor - Wit: J.A. Dailey; Claude Dailey; Emery Dailey - July 24, 1926 (no record source) See "Old" corner renewal Vol. 1 Pg. 7

-----  
Iron pipe with copper cap standard US corner marked thus:

T20S  
R10W  
S 32 | S 33  
S 5 | S 4  
T 21 S

New BTs- 14" Alder S.83°W., 8.6 lks.  
15" Fir N.45°30'W., 44 lks.  
12" Fir N.30°E., 36 lks.  
12" Alder S.5°W., 6.0 lks.

Richard J. Hintz - For: International Paper - Feb. 1982 - M 91-24

-----  
Found - I.P. with USGLO brass cap dated 1918 and a plow share.  
New BT - 14" Alder bears S.70°W., 4.7 ft., scribed.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Crew, Randy Smith - March 22, 1982 - C.S. File 61/30-19

-----  
Found - 2" I.P. filled with concrete firmly set, protruding 6" out of ground. The top 10" of said I.P. has brass cap attached and is broken off and lying on ground. Cap is an unrecorded GLO cap stamped "General Land Office Survey T20S R10W S2 S33 S5 S4 T21S 1918".

Also found unrecorded 20" x 5" plow shear along side iron pipe.

14" Alder with possible well healed blaze and newly bark scribed "S5 BT" bears S.63°W., 4.7 ft. (Rec. 5.7 ft.) bark scribed.

15" now 20" Fir stump with scribed "BT" visible bears N.32°E., 28.2 ft. (Rec. N.45°30'E., 29.0 ft.)  
(Cont. Next Page)

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5; 32 & 33, T20-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

12" now 15" Fir snag approx. 40 ft. tall with well healed blaze, bears N.30°E., 23.8 ft.  
12" Alder is gone as is any orig. evidence.  
At the location of the 2" I.P. filled with concrete, I SET a 1" x 30" I.P. with brass cap attached mkd. "Douglas Co. Surveyor T20S S32 S33 S5 S4 R10W T21S 1982." I buried both parts of found GLO I.P. and brass cap along with plow shear alongside the new brass cap.  
New BTs- 16" Fir scribed "T20S R10W S33 CS BT" in double blaze bears N.2°E., 83.8 ft.  
24" Cedar scribed "T21S R10W S4 CS BT" in double blaze, bears S.1°, 16.2 ft.  
7" Fir scribed "T21S R10W S5 CS BT" in double blaze, S.71°W., 32.9 ft.

Fd. OK by H. Wilcox, Nov. 2003 - M143-40