

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. cor. for 35 & 36 only, (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1039)

-----  
Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 35 and 36, with brass cap mkd: T21S R10W  
S35|S36  
1919

from which,

A Fir 14" dia., bears N.39°E., 39 lks. dist. mkd. T21S R10W S36 BT.

A Fir 60" dia., bears N.53°W., 82 lks. dist. mkd. T21S R10W S35 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - May 1968 - C.S. File 54/1-23

-----  
Found - No trace of I.P. or brass cap set in 1919.  
Orig. 14" now 26" Fir, turned out and slid downhill, N.39°E., 25.7 ft.  
Orig. 60" now 65" Fir, 50 ft. high snag, N.53°W., 54.1 ft., open and find scribe.

Set Brass cap at cor. mkd: County Surveyors Office  
T21S S 35|S 36 R10W  
T22S

1968

Set 6 ft. steel fence post alongside.

New BTs -14" Maple N.59°W., 47.3 ft. mkd. T21S R10W S35 CSBT.

16" D.Fir N.11°E., 57.2 ft. mkd. T21S R10W S36 CSBT.

Tony Hostetter - For: Roseburg Resources - Jan. 2020 - C.S. File 65/105-10

-----  
Fd. 1968 BC as described (1968) from which  
28" Fir bears N.11°E., to center.