

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1080)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for
¼ Sec. cor., with brass cap mkd:

¼
S 11|S 12
1919

from which

- A Fir, 8" dia., bears S.7°E., 20 lks., mkd: ¼ S12 BT.
- A Fir, 18" dia., bears N.42°W., 17 lks., mkd: ¼ S11 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Feb. 1970 - C.S. File 54/1-20

Found - No trace of 1919 IP & brass cap.
Orig. 18" now 24" D.Fir, alive, N.42°W., 11.2 ft.,
prev. opened & scribe visible. We rescribe "¼ S11
CS BT"

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T21S R10W
OFFICE 1970 ¼ S 11|S 10

New BTs- 16" D.Fir, N.25°E., 35.8 ft. mkd: ¼ S12 CS BT
14" D.Fir, S.33°W., 14.1 ft., mkd: ¼ S11 CS BT

This corner lies on very steep, easterly slope about 60 ft.
East of top of spur, ridge sloping south.