

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1250)

-----  
Set a post 4 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. marked 1/4 S on N. face, from which

An Alder 30" dia., bears N.37°E., 49 lks. dist. mkd. 1/4 S BT.

A Maple 18" dia., bears S.23°E., 100 lks. dist. mkd. 1/4 S BT.

Reported as not found DCSO BR 6/1965 C.S. 53/66-134

Douglas Co. Surveyors Office - James W. Byron, Co. Surveyor Vernon Tracy; J. Heritage; E. West, crew - June 1967 - C.S. File 54/47 and M 33-18

-----  
Found no trace of orig. corner or BTs.

Set Brass cap at cor. mkd: County Surveyors Office

T 21 S R 11 W

1/4 S 5  
S 8

1967

New BTs -18" Maple S.21°E., 57.8 ft. mkd. 1/4 S8 CS BT.

10" double Cedar (most westerly) N.23°E., 46.7 ft. mkd. 1/4 S5 CS BT.

This corner lies 10 ft. North of E-W fence extended and creek call to East fits good.

Fd OK June 27, 1977, DCSO, R. Kimberling - C.S. File 59/34-43

Survey by Ronald G. Geisler, LS #1988 - For: Champion International Corp. - Nov. 1982 - C.S. File 58/278 & M 93-34

-----  
Found - 1967 DCSO brass cap.

21" double Cedar stump, (most westerly) bears N.23°E., 46.7 ft., no scribing visible. Set 8" nail in top, center of westerly stump.

27" Maple bears S.21°E., 57.3 ft., no scribing visible.

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 3/18/1998 - C.S. File 66/2-7

-----  
Found - 2 1/2" dia. brass cap on a 1 1/2" O.D. iron pipe, protrudes 4" above ground. 1967

Cont. next page

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

18" now 27" dia., 7 ft. tall, Maple stump that has re-sprouted with a healed blaze, bears S.21°E., 57.3 ft. (Agrees with rec.) 1967  
18" now 21" dia., rotted double trunked Cedar stump, no blaze or scribing visible, bears N.23°E., 46.7 ft. to westerly trunk. (Agrees with rec.) 1967  
New BTs- 5" dia., Hemlock, double blazed and scribed "¼ S5 CS BT", bears N.52°E., 33.5 ft.  
7" dia., Alder, bark scribed, "¼ S8 CS BT" bears S.52°E., 8.0 ft.  
3" dia., Cedar, double blazed and scribed "X BT", bears S.20°E., 20.5 ft.  
Note - Corner lies 8 ft. north of an old E-W fence.