

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1160)

Set ¼ sec. post, from which
 An Alder 6" dia., bears N.72°E., 262 lks. dist.
 A Willow 5" dia., bears S.4°E., 292 lks. dist.

H.L. Eppstein, County Surveyor - Wit: Bert Lane; Grover Anchors and Harry Burnhardt - June 27, 1926 - C.S. File 4/68 (and "old" corner book Pg 16)

Set on true line between section cor. and ½ way between old corner lot. Set a ½" x 5 ft. galv. iron pipe. Marked a 24" Fir S.60°30'E., 506 lks.

Survey by R.J. Hintz - For: Brandon - Aug. 1973 - C.S. File 55/310

Set 1" Iron rod 6" below the surface of the ground.
Found - 40" Fir stump, bears S.60°30'E., 334.0 ft.
 Power pole 10 - 8 bears S.73°E., 7.0 ft., place
 15 metal tag on pole.

Fd. OK June 1988 by R. Hintz - M 106-29 A & B
Fd. OK June 1996 by J. Estabrook - M125-23