

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 423400

PRIMARY CORNER DESCRIPTION M.C. So. bdy. Sec. 15

Alias <u>841280</u>	Description <u>M.C. right bank Umpqua River</u>
Alias <u>037060</u>	Description <u>Pt. on line of DLC #37</u>
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1280)

To "right" bank of Umpqua River. (Typed notes says left bank but I believe only makes sense to be "right" bank. V.Laugen, 10/1995)

Set post, raised mound with trench as per instructions.

Ben B. Irving, D.C.S. - Wit: N.E. Richardson and Loren Weber - July 19, 1940 - C.S. File 16/55 and ("old" renewal vol. 1 Page 16)

Location determined from line West from sec. cor. 14, 15, 22 and 23, and falls in a drainage ditch.

Set a 6" x 6" x 15" block of concrete in top of dike, 33 ft. West of corner, for a witness corner and set 2" x 6" x 48" post alongside.

Jerry Estabrook - For: IP CO. - 6/2007 - M153-34 A-D

CALCULATED POSITION ONLY

Meander corner was calculated by holding rec. distance 3634.40' from the section corner common to sections 14, 15, 22, & 23 per M2-25 and the rec. distance 2401.71' from meander corner common to secs. 15 & 16 per M1-5