

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T22-12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1265)

-----  
Set post cor. of secs. 1, 2, 35 and 36, from which  
A Spruce 50" dia., bears N.30°E., 17 lks. dist.  
A Hemlock 36" dia., bears S.86°E., 72 lks. dist.  
A Cedar 12" dia., bears S.28°W., 61 lks. dist.  
An Alder 18" dia., bears N.34°W., 52 lks. dist.

Oregon State Highway Dept. - Reedsport to Hinsdale Slough  
Drg. No. 4B-21-22 - Aug. 1934 (DCSO records, A-1)

-----  
Bearings found, Cor. Set.

Douglas Co. Surveyors Office - James Byron, Deputy - John M. Powell and crew - For: Douglas County - Feb/June 1971 - C.S. File 56/5-9 and M 42-27

-----  
Found - 48" Cedar stump S.66°E., 47.6 ft., fragmentary scribing found. High cut Cedar stump shows old axe work and possible scribe marks made at least 60 years ago (ring count). Checks call to creek and checks dist. for orig. SE. BT.

No orig. BTs found.

Old squared stake at approx. location of corner lying on ground. Also find old blazed trees West of this.

Set Brass cap at cor. mkd: County Surveyors Office  
T21S R12W S 35 | S 36  
T22S S 2 | S 1  
1971

New BTs- 16" D.Fir N.35°W., 30.3 ft. scribed T21S R12W S35 CS BT.

9" Alder N.87°E. 23.0 ft scribed T21S R12W S36 CS BT

6" Alder S.40°E., 24.9 ft scribed T22S R12W S1 CS BT

8" Alder S.78°W., 12.4 ft scribed T22S R12W S2 CS BT

This corner lies 10.0 ft. W. of creek, checks call.

B.L.M. resurvey by Deborah M. Stephens and Harvey E. Wofford dated April 1990 thru April 1995 under group #1521 (DCSO records Vol. 51 Page(s) 19638-39)

-----  
The cor. of secs. 1, 2, 35 and 36, restored by person(s) unknown and remonumented by Byron in 1971. There is no remaining evidence of the original corner, therefore this position is accepted as the corner; monumented with an iron post, 1 in. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd. (Cont. Next Page)

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T22-12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

COUNTY SURVEYORS OFFICE

T21S R12W

S35 | S36

S2 | S1

T22S

1971

from which the remains of bearing trees mkd. by Byron  
An alder, 8" dia., bears N.87°E., 35 lks. dist., no marks visible on an open, decayed blaze.  
An alder snag, 8" dia., bears S.40°E., 37½ lks. dist., no marks visible on partially healed blaze.  
An alder, 9" dia., bears S.74½°W., 19 lks. dist., with scribe marks T22S R12W S2 CS visible on partially healed blaze.  
A fir, 23" dia., bears N.35°W., 43½ lks., with healed blaze.  
and a bearing tree mkd. by person(s) unknown  
A cedar, 48" dia., bears S.66°E., 72 lks., no marks visible on opened blaze.

Found OK by S. Mitchell, Dec. 2002 - M141-40

Tony Hostetter - For: Rome Creek Timber - Feb. 2019 - M175-35

-----  
Found - 1971 brass cap as described by DCS0  
Corner is in a new clear cut all BTs are stumps.  
48" Cedar stump, no marks, placed new tag, bears;  
S.66°E., 47.6 ft to center.  
26" Fir, no marks, placed new tag bears; N.35°W.,  
30.3 ft to center.

Stephen Stys - For: Roseburg Resources Co. - 5/2023 - M182-49

-----  
Found - A 2½" brass cap on a 1" IP, set per map M42-27  
Marked incorrectly:

COUNTY SURVEYORS OFFICE

T22S

S35 | S36

S 1 | S 2

R12W

1971

A 26" Fir stump, with no visible marks and tag bears  
N.35°W., 30.3'. (MAP FILE M42-27)  
A 48" Cedar stump, w/healed face and tag bears  
S.66°E., 47.6'. (MAP FILE M42-27)