

TOWNSHIP 21 RANGE 12 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 12 & 13; 7 & 18, T21-11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1152)

-----  
Set post cor. of secs. 7, 12, 13 and 18, from which  
A Hemlock 24" dia., bears N.23°E., 16 lks. dist.  
A Spruce 48" dia., bears N.19°W., 9 lks. dist.  
A Spruce 36" dia., bears S.64°W., 72 lks. dist.  
A Hemlock 24" dia., bears S.8°E., 50 lks. dist.

Survey by Harry Hugill - For: Walter Pyritz - Jan. 15, 1949 - C.S. File 40/169

-----  
At sec. cor., I find marked by an Iron pipe with old BTs evident.

Douglas Co. Surveyors Office - James Byron, Deputy - John M. Powell and crew - April 1, 1970 - C.S. File 54/110

-----  
Found - 1½" Iron pipe in poor condition.  
Orig. 24" now 36" Hemlock, badly decayed remains of stump, N.23°E., 10.6 ft., no scribe found.  
Orig. 48" now 50" Spruce, badly decayed stump, N.19°W., 5.9 ft., scribe visible on old blaze.  
Other orig. BTs would have been destroyed by very old logging road, no unusable.

Set Brass cap at cor. mkd: County Surveyors Office

R	T 21	S	R
12	S 12	S 7	11
W	S 13	S 18	W

1970

Reset old pipe and old 5/8" Iron rod found while digging.  
New BTs -10" Cedar N.31°E., 26.0 ft. mkd. T21S R11W S7 CS BT.  
12" D.Fir S.53°E., 16.6 ft. mkd. T21S R11W S18 CSBT  
12" Cedar S.15°W., 5.2 ft. mkd. T21S R12W S13 CS BT.  
12" Cedar N.61°W., 14.3 ft. mkd. T21S R12W S12 CSBT  
This corner lies about 100 ft. N. of slough, course NW. and 20 ft. N. of old logging road, course NW.

Fd. OK, 12/1984 by R. Ward - C.S. File 58/146-12

Fd. OK, Jan. 1988 by R. Ward - C.S. File 63/70