

TOWNSHIP 21 RANGE 13 POINT IDENTIFIER # 700140

PRIMARY CORNER DESCRIPTION 1/4 Cor for Sec. 36; & 31 of T21-12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #68 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1261) and (Vol. 1 Page 5)

-----  
1/4 sec. cor. is in quicksand.

BLM resurvey by Glenn F. Goodson, Scott R. McIntyre and Scott R. McMullin, Cadastral Surveyors - Under Group #1064 - Surveyed June/Sept. 1981 - (DCSO records Vol. 44 Page(s) 17190)

-----  
Point for the 1/4 sec. cor., at record distance; there is no remaining evidence of the original corner.  
Set an alum. rod, 10 ft. long, 5/8" dia., 9 ft. in the ground, in concrete, with alum. cap mkd:  
T 21 S  
R 13 W R 12 W  
1/4  
S 36 S 31  
1981

No suitable trees available within limits.  
Set a steel fence post alongside aluminum rod.