

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 039010

PRIMARY CORNER DESCRIPTION NE Cor. McDonald DLC #39

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,  
dated Sept. 1856

-----  
Set post NE. cor. Cl. 39, from which  
A Fir 20" dia., bears N.25°E., 88 lks.  
An Oak 24" dia., bears N.45°W., 144 lks.

Survey by Daniel Baker - For: Weyerhaeuser Co. - Nov. 1994 -  
M 119-20

-----  
Found - Broken stone at base of fence corner post per M61-  
79.  
36" burnt stump, N.26°E., 61.0 ft. no marks remain.  
Set 2" x 42" iron pipe with brass cap marked "T22S R4W NE DLC  
39 S20 PLS 1978 1993", stones placed alongside.  
New BTs -14" Fir, N.64°W., 7.8 ft. to "W" nail, scribed "NE  
DLC 39"  
20" Fir, S.6°E., 4.3 ft. to "W" nail, scribed "NE  
DLC 39"  
6 ft. fence post, 1 ft.