

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 7; and 12 of T22-5

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1335)

Set ¼ sec. post, from which
A Fir 35" dia., bears N.47°E., 17 lks. dist.
A Fir 40" dia., bears N.75°W., 79 lks. dist.

B.H. McGillicuddy - For: Whipple Lumber Co. - April 1952 - RM 1-40

CORNER REPORT ONLY
Found - Post and 2 original BTs:
Fir 35", N.47°E., 17 lks., stump.
Fir 40", N.75°W., 79 lks., burned windfall.

Douglas Co. Surveyors Office - Bruce Rogers, Deputy, Stone and Stoffel, crew - June 2, 1965 - C.S. File 53/101-19

Corner not found.

Dan Baker - For: Rocking C Ranch - 6/1999 - M 132-5

Set - 2"x30" iron pipe with brass cap mkd:
T22S
¼
S 12|S 7
R5W R4W
PLS 1978
1999
8" Fir, S.56°E., 2.7 ft. - side center.
12" Fir, N.41°E., 10.9 ft. - side center.
12" Hemlock, N.38°W., 9.0 ft. - side center.
7" Fir, N.77°W., 15.2 ft., side center.

FD Ok on BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #2002, surveyed Jan/March 2002- (DCSO rec. Vol. 54 Page(s) 20812-3)