

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias 039030 Description SW Cor. McDonald DLC #39
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1347)

Set sec. post, from which
A Hemlock 4" dia., bears N.85°W., 45 lks. dist.
A Maple 12" dia., bears S.40°E., 110 lks. dist.

Douglas County Surveyors Office - James W. Byron, Surveyor
Bruce Rogers, and crew - C.S. File 53/101-58 - Dec. 21, 1964

Corner searched for, not found.