

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1350)

Set ¼ sec. post, from which
A Cedar 40" dia., bears N.37°E., 59 lks. dist.
A Cedar 36" dia., bears S.68°W., 23 lks. dist.

Douglas County Surveyors Office - Milo E. Godfrey - Sept. 1962 - C.S. File 49/42-65

Corner searched for, not found. (Oral request by Mr. Glen Coons. No trace of cor. or bearing trees found.)

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #2002, surveyed Jan/March 2002- (DCSO rec. Vol. 54 Page(s) 20818)

Point for the ¼ sec. cor. of secs. 7 & 8 at proportionate dist. There is no remaining evidence of the orig. cor. Set a stainless steel post, 28" long, 2½" diam., 26" in the ground, with brass cap mkd.

T22S R4W
1/4
S 7 | S 8
2002

from which
A fir, 11" dia., bears N.47¾°E., 28.8 ft., mkd. ¼ S8 BT.
A fir, 4" dia., bears N.50½°W., 10.3 ft., mkd. X BT.
Each new bearing tree has a 2½" X ¼" magnetic nail (MAG-NAIL) driven at the base on the right side-center.

Deposit a magnet in a white plastic case at the base of the stainless steel post.