

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6 and 31 & 32, T21-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCS0 records Vol. 2 Page(s) 753)

-----  
Set post cor. of secs. 5, 6, 31 and 32, from which  
A Fir 30" dia., bears N.60°E., 80 lks. dist.  
A Fir 12" dia., bears S.4½°E., 39 lks. dist.  
A Fir 10" dia., bears S.11½°W., 45 lks. dist.  
A Fir 15" dia., bears N.60°W., 58 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon "Ray" Tracy, crew - Sept. 1962 - C.S. File 49/42-61

-----  
Found - Old Fir stump, now 42" dia., N.60°E., 52.8 ft. Found traces of old bark scribing, probably 50 yrs. old or more. "CS" is all that is legible. I believe this to be the orig. NE. BT which was later bark scribed.

No trace found of the other 3 orig. BTs.

A Fir tree, approx. 10 ft. North of corner has N. & S. line blazes approx. 20 years old.

Set Brass cap at cor. mkd. County Surveyors Office

S31	S32	T21S	
S 6	S 5	T22S	R4W

1962

New BTs - 14" W.Fir N.32°E., 18.0 ft. mkd. T21S R4W S32 CS BT  
18" D.Fir N.50°W., 15.3 ft. mkd. T21S R4W S31 CS BT  
9" W.Fir S.30°E., 30.8 ft. mkd. T22S R4W S5 CS BT.  
13" D.Fir S.17°W., 58.4 ft. mkd. T22S R4W S6 CS BT.

A fence corner, fences West and SE., bears S.65°W., 4.5 ft.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy and crew - Dec. 27, 1968 - C.S. File 54/14-41

-----  
Found - 1962 DCS0 brass cap, properly mkd., and firmly set.  
14" now 15" W.Fir, alive, N.32°E., 18.0 ft., nearly healed blaze, scribing visible.

18" now 19" D.Fir, alive, N.50°W., 15.3 ft., nearly healed blaze.

13" now 14" D.Fir, alive, S.17°W., 58.4 ft., blaze healed.

SE. BT down.

New BT - 13" R.Fir S.71°E., 91.4 ft. mkd. T22S R4W S5 CS BT.  
Probable orig. BT stump still in place.

This corner lies N.65°E., 4.5 ft. from fence corner, fences E-W and S.

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6 and 31 & 32, T21-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by Wayne L. Rogers; Dale T. Bedell; Boyd W. Peterson; Garry L. Moore, Cadastral Surveyors and Garry L. Moore, Surveying Technician - Under Group #1406, Surveyed Feb. 2, 1988/Jan. 6, 1989 - (DCSO records Vol. 48 Page(s) 18600)

-----

The sec. cor., perpetuated and recorded by Godfrey in 1962, monumented with an iron post 1¼" dia., firmly set, projecting 10" above ground with properly mkd. brass cap from which the remains of an original bearing tree

A sawed Fir stump 44" dia., bears N.60°E., 80 lks. dist., no marks visible.

and the remains of bearing trees mkd. by Godfrey

A Fir 22" dia., bears N.31°E., 27 lks. dist. with healed double blaze.

A sawed Fir stump 14" dia., bears S.32¼°E., 47 lks. dist. no marks visible.

A Fir 26" dia., bears S.17°W., 88 lks. dist. with healed double blaze.

A Fir 31" dia., bears N.50½°W., 22½ lks. dist. with healed double blaze.

and a new bearing tree

A Fir 6" dia., bears S.58¼°E., 38½ lks. dist. mkd. T22S R4W S5 BT.

Fd. OK, Dec. 1994 by Les Roberts - M 121-26

Fd. OK, May. 2000 by Les Roberts - M134-76

Fd. BC 7/2014 by D. Edwards - M168-28