

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 3 Page(s) 1336)

Set post cor. of secs. 27, 28, 33 and 34, from which

- A W.Oak 6" dia., bears S.2°W., 717 lks. dist.
- A W.Oak 36" dia., bears S.69°E., 278 lks. dist.
- A B.Oak 24" dia., bears N.9°E., 274 lks. dist.
- A B.Oak 18" dia., bears N.19°W., 400 lks. dist.

O.F. Thiel - For: Kit Letsom - 10/23/1950 - Thiel FB 20 Pg 1

All old trees gone but stump of SE with marks on slab of tree. Reestablished cor. from this. NW fallen and NE entirely gone. Marked:

- W.Oak 28" bears N(?)W(?), 128 ft.
- W.Oak 22" S.15°W., 36 ft.
- Fir 55" dia., N.13°E., 177 ft.
- B.Oak 24" S.50°E., 120 ft.

Set an Iron corner.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon Tracy - Aug. 1963 - C.S. 49/59-42 (See C.S. 49/59-37 for May 1963 Fd report)

Found - Badly rotted old Oak stump S.69°E., 183.5 ft., portion of stump lying alongside shows good reverse scribing. Ray Miller remembers chopping this piece out of stump about 10 years ago when corner was found and renewed by O. Thiel.

Remnants of old Oaks to NE. and NW. which approx. fit brg. and dist. for orig. NE. and NW. BTs. No marks found.

No trace of original SW. BT.

Set Brass cap at cor. mkd: County Surveyors Office

T	22	S	R	4	W
		<u>S28</u>		<u>S27</u>	
		<u>S33</u>		<u>S34</u>	
				1963	

Rescribe Thiel's trees approx. 10 yrs. ago for BTs:

- 26" W.Oak S.16°W., 39.9 ft. mkd. T22S R4W S33 CSBT
- 24" B.Oak S.49°E., 121.2 ft. mkd. T22S R4W S34 CSBT
- 33" W.Oak N.13½°W., 127.5 ft., shows good scars, healed over. Didn't remark.
- 58" D.Fir N.10°E., 175.4 ft. mkd. T22S R4W S27 CSBT

A 1¼" Iron rod and square Fir stake bears S.36°W., 4.2 ft. Corner lies on very steep, grassy South slope, evidence of old slide area.

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

William L. Wilt - For: Weyerhaeuser Co. - Aug. 22, 1963 -
C.S. File 53/105-30 & C.S. File 51/87-8

GLO survey record, 1856:

6" W.Oak S.2°W., 717 lks.; No evidence found (in area of landing)

36" W.Oak S.69°E., 278 lks.; approx. 40" tree, rotted and fallen. Stump badly rotted in orig. position. Found good negative of legible scribing on slab lying on ground.

24" B.Oak N.9°E., 274 lks., stump hole.

18" B.Oak N.19°W., 400 lks.; 30" uprooted Oak, face burned out.

1963 County record:

Brass cap/iron pipe, new condition.

26" W.Oak S.16°W., 39.9 ft., new condition. (rescribed)

24" B.Oak S.49°E., 121.2 ft., new condition. (rescribed)

33" W.Oak N.13½°W., 127.5 ft., healed scar. (not rescribed)

58" D.Fir N.10°E., 175.4 ft., new condition (rescribed)
Old scribing is bark scribed.

Accessories added this date: ("W" nails and plates)

24" B.Oak S.55°E., 119.1 ft. (1963 Co. BT)

24" W.Oak S.14½°W., 39.2 ft. (1963 Co. BT)

33" W.Oak N.13°W., 124.9 ft. (1963 Co. BT)

54" D.Fir N.9°E., 172.6 ft. (1963 Co. BT)

BLM Dependent resurvey by A. Bert Skeesick Cadastral Surveyor, and Robert H. Browning, Surveying Tech. Group No. 2170 surveyed Aug. 2007/Feb. 2008 - (DCSO records Vol. 55 Page(s) 21795)

The cor. of secs. 27, 28, 33, & 34, perpetuated by Thiel in 1950, subsequently perpetuated by Godfrey, in 1963, from original evidence no longer in existence, monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.

from which the remains of the bearing trees mkd. by Thiel

A fir, 65" dia., bears N.10¾°E., 175.4 ft., with a healed blaze.

An oak, 19" dia., bears S.47½°E., 119.2 ft., with a healed blaze.

An oak, 34" dia., bears S.17¼°W., 39.8 ft., with a healed blaze.

An oak, 47" dia., bears N.20¼°W., 180.2 ft., with a healed blaze.