

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO Survey by Wm. Thiel under Contract #321 dated April 11, 1879 - (DCSO records Vol. 4 Page(s) 1358)

-----  
Set ¼ sec. post, from which  
A Laurel 6" dia., bears S.22¼°E., 52 lks. dist.  
A Laurel 8" dia., bears S.74°W., 51 lks. dist.

Wilford N. Haines - For: Whipple - (Date ?) (Received from Haines Estate and filed Sept. 1990) H. En. 6

-----  
1" Iron pipe.  
Laurel 6", S.22½°E., 52 lks.  
Laurel 8" S.74°W., 51 lks.  
Had to set this corner.

Nick Juliano - For: Rickini Lumber Co., Saginaw, Oregon - Dec. 22, 1958 - M 13-55

-----  
Set 1/2" Iron pipe in a mound of stone, from which  
16" Madrone N.89°W., 29.0 ft. with alum. sec. plat marker.  
16" Madrone S.50°E., 67.3 ft. with alum. sec. plat marker.

Cor. OK, Jan. 1965 by B. Rogers, DCSO C.S. File 53/101-81

Bruce Shaner - For: Sehlin Land & Logging LLC - Sept. 13, 2001 - C. S. File 65/37-21F

-----  
Found - ½" Iron pipe gone , but from position of pipe, BTs were found as:  
20" Madrone BT stump with old face @ "BT", bears S.50°E., 67.3 ft.  
16" Madrone BT, tree now gone but with portion of stump & roots present, bears N.89°W., 29.0 ft.  
Set - 3" alum. cap mkd: T22S R4W W.M. ¼ S S22|S23 RLS 430 2001, in 1 sack of P.C. concrete as monumented on rock faced SW slope.  
10" D.Fir BT, I scribed "¼ S22 BT" bears S.63°W., 41.0 ft.  
10" D.Fir BT, I scribed "¼ S22 BT" bears N.55°W., 77.0 ft.  
No BTs in sight in sec. 23.  
Note - ¼ Corner is 200 ft. West of N-S logging spur. Set steel fencepost & tag on road.

continued next page

TOWNSHIP 22 RANGE 04 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM Dependent resurvey by A. Bert Skeesick Cadastral Surveyor, and Robert H. Browning, Surveying Tech. Group No. 2170 surveyed Aug. 2007/Feb. 2008 - (DCSO records Vol. 55 Page(s) 21788-9)

-----

The ¼ sec. cor. of secs. 22 & 23, reestablished by Juliano, in 1958, subsequently perpetuated by Shaner, in 2001, and is accepted as the cor., monumented with an aluminum cap, 3" dia., firmly set in concrete, with top (properly) mkd. from which the remains of bearing trees mkd. by Juliano

A decayed madrone stump, size indeterminate, bears S.49¼°E., 67.1 ft., no marks visible.

A root hole bears N.85½°W., 28.8 ft., with fallen, decayed madrone stump, size indeterminate, lying alongside, no marks visible.

and bearing trees mkd. by Shaner

A fir, 14" dia., bears S.65°W., 39.9 ft., with a healed blaze.

A fir, 15" dia., bears N.48°W., 77.2 ft., with a healed blaze.

and a new bearing tree

A fir, 7" dia., bears N.60¼°E., 123.6 ft., mkd. ¼ S23 BT.