

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 040050

PRIMARY CORNER DESCRIPTION SW Cor. Warren Goodell DLC #40

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated Sept. 1856

Beginning at the SW corner in Sec. 17, from which
 An Oak 24" dia., bears S.12½°W., 1072 lks.
 An Oak 18" dia., bears S.60°E., 445 lks.
(Did not say in notes that Hathorn "Set a stone post")
(VL, 2/1995)

Wilford N. Haines - M 24-23 - Oct. 1962

1½" Iron pipe knocked down by farming operations.
Set 1" x 1" x 36" T Iron.

Wilford N. Haines - Dec. 30, 1967 - M 35-16

Found - 2" Iron pipe, T-Iron gone.
Drove 5/8" x 60" Steel rod in center of pipe.

Fd. 2" pipe, July 13, 1984, J. Dix, OSHD, C.S. File 63/9-2

Fd. OK, Dec. 1992, K.Hoffine, Land partition 1993-0049

Ken Hoffine, L.S. #2291 - For: Lone Rock Timber Co. June 1995
- M 119-66

Found - 5/8" iron rod badly twisted
Set - A 5/8"x40" iron rod, with 1½" alum. cap mkd: LONE
ROCK TIMBER COMPANY T22SR5W S17 DLC 40 1995 PLS
2291, at base of existing rod.
8" D.Fir bears N.57°E., 10.8'. We scribe "BT" & tag.
9" D.Fir bears S.1°E., 11.1'. We scribe "BT" & tag.
Note - Corner lies in machine planted reprod. We put a
metal fence post approx. 1.0 feet south.