

PRIMARY CORNER DESCRIPTION Sec Cor for 7 & 18; 12 & 13, T22-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1385)

-----  
Set post cor. of secs. 7, 12, 13 and 18, from which  
A W.Oak 12" dia., bears S.40½°E., 136 lks. dist.  
A Fir 24" dia., bears N.69½°E., 110 lks. dist.  
A Fir 6" dia., bears S.80°W., 89 lks. dist.  
A B.Oak 6" dia., bears N.21°W., 30 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S.A. Bilow - For: W.E. Clevenger - June 19, 1959 - C.S. File 49/158 and M 15-18

-----  
Found - Orig. 24" now 48" partly rotted Fir stump, I open and find good scribing "BT", N.69½°E., 72.6 ft. Rotted Fir stump that checks bearing and dist. for original SW BT, no scribing found. No trace of orig. SE or NW BTs found.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S  
R6W 

S 12	S 7
S 13	S 18

 R5W  
1959

New BTs -14" R.Fir bears S.16°E., 22.1 ft. scribed S18 T22S R5W CS BT.  
10" R.Fir bears S.79°W., 16.0 ft. scribed S13 T22S R6W CS BT.  
12" R.Fir bears N.35°E., 15.7 ft. scribed S7 T22S R5W CS BT.  
12" R.Fir bears N.42°W., 20.8 ft. scribed S12 T22S R6W CS BT.

I find stake marked approx. sec. cor., bears N.42°W., 30.0 ft. from section corner.

Fd. OK, April 2, 1965, DCSO, B.Rogers, C.S. File 53/101-16  
Fd. OK, June 19, 1984, M. Havig, C.S. File 58/164  
Fd. Ok by H.Christensen, Jan. 1995 - M 123-34  
Fd. OK by J. Branch, Feb. 1999 - M129-33

DCSO-GIS Corner visitation - 11/2/2005 - Typed: 1/13/2011 - C.S. File 67/33-1

-----  
Monument - 1¼" IP w/BC Comments - 2 Live BTs, 2 stumps

continued next page

PRIMARY CORNER DESCRIPTION \_\_\_\_\_

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by A. Bert Skeesick & Timothy J. Moore, Cadastral Surveyors & Robert H. Browning, Surveying Technician under Group No. 2133 surveyed April/May 2006 - (DCSO records Vol. 55 Page(s) 21710-1)

-----  
The cor. of secs. 7, 12, 13, and 18, on the W. bdy. of the Tp., perpetuated by Byron, in 1959, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd from which the remains of an original bearing tree

A decayed fir stump, 33" dia., bears N.69½°E., 72.6 ft., with scribe marks T22S visible on an opened blaze. and the remains of bearing trees mkd. by Byron

A fir, 26" dia., bears N.34½ E., 15.8 ft., with a healed double blaze.

A fir, 25" dia., bears S.18°E., 21.8 ft., with a healed double blaze.

A sawed fir stump, 16" dia., bears S.78½°W., 15.9 ft., with a healed double blaze.

A sawed fir stump, 23" dia., bears N.41¼°W., 20.4 ft., with a healed blaze.

and new bearing trees

A fir, 10" dia., bears S.57¼°W., 5.6 ft., mkd. T22S R6W S13 BT.

A fir, 13" dia., bears N.19°W., 14.0 ft., mkd. T22S R6W S12 BT.