

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 146100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor Sec. 6 only, T23-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2338)

-----  
Set ¼ sec. post, from which  
A Y.Oak 16" dia., bears S.89¼°E., 587 lks.  
A Fir 36" dia., bears S.22 ¾°W., 1074 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S. Bilow - March 4, 1958 - C.S. File 49/59-19

-----  
Found - Orig. 16" now 34" B.Oak S.89¼°E., 387.2 ft. This BT rescribed about 25 years ago, I open back of this face and find good scribing on original face.  
Orig. 36" Fir now 40" rotted stump S.22 ¾°E., 708.4 ft., good scribing visible on section of old face.

Set Brass cap at cor. mkd: County Surveyors Office

N 1/4 S 6 T23S R5W  
New BT - 3" W.Oak bears S.65°E., 49.2 ft. scribed ¼ S6 CSBT  
No other trees near.

Fd. OK, Bruce Rogers, Feb. 1965 C.S. File 53/101-25

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 6/19/2003 - C.S. File 66/58-15A-C

-----  
Found - 1958 DCSO BC/IP pipe protrudes 15" out of ground. 16" Now 30" dia., down & rotted B.Oak showing signs of being previously opened, no scribe visible, root hole agrees well with rec. S.89¼°E., 387.2 ft. (OBT)

Orig. D.Fir BT not looked for as it was a rotted stump in 1958.

3"? now 22" dia., W.Oak no blaze visible bears S.65°E., 49.2 ft. (1958)

New - 23" dia., W.Oak (S¼ Sec. 31 BT) with SW'ly blaze scribed in 1958, bears N.4½°E., 256.5 ft.

1958 DCSO BC/IP S¼ S31 bears N.89¼°W., 337.0 ft.  
Corner is approx 45 ft. West of an old 4-way fence corner.

Compass decl. 17½°E.

continued next page

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 146100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor Sec. 6 only, T23-5

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Following positions are for location purposes only  
NOT SURVEY GRADE

Equipment: Trimble GEOEXPLORER 3 System  
File: R062418A  
Point Name: NQ T23SR5W S6 ONLY

	<u>1927</u>				<u>1983</u>	
OCS	N	719547	E	1249236	N	E
Latitude:		43°36'22.2"			Latitude:	
Longitude:		123°20'06.2"			Longitude:	
Offset to corner?				NO		
Corrected for?						



DCS0-GIS Corner visitation - 11/30/2005 - Typed: 1/13/2011 -  
C.S. File 67/33-1

-----  
Monument - 1¼" IP W/BC      Comment - OK