

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec Cor for 16, 17, 20 and 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1406)

-----  
Set post cor. of secs. 16, 17, 20 and 21, from which  
A W.Oak 10" dia., bears S.15°W., 46 lks. dist.  
Erected stone mound.

Volume 2 Page 264 (date?) (Probably by Thiel)

-----  
Marked R.Fir 16" dia., from which  
R.Fir 10" bears N.59°00'E., 16 lks.  
R.Fir 13" bears S.26°00'E., 23 lks.  
R.Fir 13" bears S.53°40'W., 34 lks.  
R.Fir 10" bears N.40°45'W., 34 lks.  
(Old BTs (?) in evidence)

Douglas Co. Surveyors Office - Bruce Rogers, Deputy, Stone and Stoffel, crew - Feb. 9, 1965 - C.S. File 53/101-31

-----  
Corner not found.

Corner not found, June 1973, Woolley Logging

Wilford N. Haines - For: Field & Stream Real Estate Inc. - Aug. 6, 1975 - M 57-66

-----  
Found - 3/4" Bolt.  
Orig. Oak BT, S.15°W., 46 lks. was here 15 or 20 years ago.  
No trace of trees shown in prior visit was ever found by me.  
Area has been cleared and burned. Only the bolt remains.  
New BT - 40" I.Cedar bears N.71°W., 16.8 ft.  
Set 5/8" Rebar on line. [N.89°19'E., 806.51 ft - east side of Elk Creek- added 4/25/2016 JC DCSO]