

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1408-09)

-----  
Set ¼ sec. post, from which  
A Fir 48" dia., bears N.76°W., 54 lks. dist.  
A W.Oak 8" dia., bears S.35°E., 39 lks. dist.

N.E. Richardson, Deputy - Wit: Godfrey and Kershner - Feb. 11, 1948 (No record source found)

-----  
Set 1" galv. Iron pipe with a brass cap mkd. C.S. T22S R5W ¼ S8-9, from which  
15" Chinquapin bears N.30¼°E., 195.4 ft.  
W.Oak, orig. BT, bears S.30°E., 25.7 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; A. Bilow - Oct/Nov. 1957 - C.S. File 49/19

-----  
Found - Orig. 6" now 43" W.Oak S.30°E., 25.7 ft. This opened by Richardson in 1948. Orig. scribe "BT" visible. Brass cap set by Richardson, NOT FOUND. High fill now covers this area.  
Chinquapin scribed in 1948, NOT FOUND.

Set Brass cap at cor. mkd: County Surveyors Office  
T 22 S R 5 W  
¼ S8|S9  
1957

New BTs -I rescribe orig. 43" W.Oak S.30°E., 25.7 ft. "¼ S9 CS BT"  
6" R.Fir bears N.56°E., 156.1 ft. scribed "¼ S9 CS BT"

Douglas Co. Surveyors Office - Larry E. Monrean, deputy - Terrie Plouff - Sept. 24, 1981 - C.S. File 61/27-53

-----  
Found - 1" I.P. with brass cap properly stamped. Cap is found badly bent and laying flush with ground. As indicated in prior renewals, this monument set with original BT at S.30°E. (Rec. S.35°E.) We are unable to find any information to clarify this discrepancy. We agree with position of the true corner determined by Robert Dean, C.S. File 58/207, from which the monument set by Byron bears N.43°E., 2.93 ft.

48" W.Oak, orig. 8", with open face scribing BT visible, bears S.35°E., 25.7 ft.

(Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 300540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

16" R.Fir, orig. 6", with faint double blaze, bears N.55¼°E., 158.0 ft. (Rec. N.56°E., 156.1 ft. from Byron position)  
Orig. 48" Fir BT, not found.  
Chinquapin from 1948, not found.  
At True Corner, We set a 1" x 30" I.P. with brass cap attached, stamped: Douglas County Surveyor T22S ¼ S8|S9 R5W. We obliterate marking on cap set by Byron.  
New BTs -We blaze an X in bark of the aforementioned 16" R.Fir.  
9" Fir scribed "¼ S8 CS BT" in double blaze, bears S.9½°W., 100.9 ft.  
16" Fir scribed "¼ S8 CS BT" in double blaze, bears S.40½°W., 202.7 ft.

Found OK by L. Roberts, July 2000 - 2000-0051 A&B  
Found OK by D. Edwards, Aug. 2002 - 2002-0035  
Fd. BC 8/2022 - M Heimburger 2022-0039B